APR 06 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SECTION

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of

PA Of 1990 On 12/14 1008
Met HACITRES
Chairman

For corners in MENOMINEE Located in: Corner Code #	BPA 9
(County)	RECEIVED 9 JAN 2 9 JAN 2 ARB # 7 REGISTE FENOMBLE
1. Public Land Survey	ENGLA FOR
2. Property Controlling S T R S S T R S S T R S S T R S S T R S S S T R S S T R S S S S	RECORD RECORD RECORD RECOR DEEDS 149858
Property in Sec. S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	- ABCDEFGHIJKL:
(SAME AS CORNER G-01, T36N - R27W)	2 - 6 - 5 - 4 - 3 - 2 - 1 - 1 - 1
	3
william Lenca, in a field survey on Aug. 17, 19, 98 do hereby state requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 ab conformance with regulations and rules therefore as required in the current manual of survey instruct United States Department of the Interior, Bureau of Land Management or by a decree of a Court of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, michigan processed before the conformance with the rules of the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, michigan processed before the conformance with the rules of the conformance with respect to the conformance with respect	uctions of the flaw and /or 6 18 17 16 15 14 13 the Michigan
recovered, found as expressed below:	9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
	11 30 33 34 35 36
	12 31 32 33 30 30
A. Description of original monument and accessories and/or subsequent restoration:	:
21 lks. All original evidence for this corner has been destroyed by Coriginal Survey by Francis Coleman (Sectional Subdivision) - B.T.'s - 29 lks. All original evidence for this corner has been destroyed by Coleman (L.C.R.C. No. 305 by William Lenca, RLS No. 26461, states "Set corresponding to the wire fence to the west. This position checks well with GLO 18 B.P N60°E - 37.32'; 10" Elm - Scr NBT - S16°E - 110.68'; PP - S3	rner in center of N-S Co. Rd. and in line with ancient ties N-S-W." Set 3/4" x 18" Iron Pipe: Fc Post - Scr.
B. Description of corner evidence found and/or method applied in restoring or reesta	ablishing corner:
We recovered a 3/4" x 18" Iron Pipe in the centerline of a North - South Counfence to the West per L.C.R.C. No. 305. We also recovered the Elm B.T. and corner falls 12' North of a County Road centerline to the East. This position 117 years, and is accepted as the best available evidence of the position of the o	has been consistently used by local surveyors for at least original corner.
C. Description of monument for corner and accessories established to perpetuate loc	WELL THE STATE OF
Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corner	
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" Metal Survey Sign Post	N48°E 33.55 feet 1' N. of Road Sign S36°E 56.15 feet 1' W. of Fence Post S39°W 60.09 feet 1' E. of P.P. N75°W 25.22 feet @ Sign Post N75°W 26.1 feet
NOTE: All bearings are magnetic bearings. All distances are measured with	th steel tape. Distances to trees are to nail in side of tree.
Signed by 10) Wain Frien	DateAug. 25, 1998
Surveyor's Michigan License No. 26461	