SURVEY & REMONUMENTATION

OCT 27 1995

ĺ	061 2 7 <u>1995</u>					Approved by Menominee County Land Survey Ramonumentation
ı	QCATIA:					Poor Group Under Act 345 Of
	SECTION	LAND CO	RNER REC	ORDATION CERT	IFICATE	PA 01200 (a 10/1 199 9 9
ı	For corners in	g 17	-doughteline	of Act 74, Mich. P.A	. 1970	MIEL-BAUS PLS
-	MENOMINEE Locate	ed (n:	Corner Code	. ш		COLUMN TO THE PARTY OF THE PART
- [(County)		Comer Code	: #		### 3
ł	Public Land Survey	T_36NR281	017	.		CCCIVED FOR NEDRO O OCT 15 PM 1: 1 RECUSTER OF DEEDS REGISTER OF DEEDS REGISTER OF DEEDS
1		T R	w	<u>.G-12</u>	{	THE THE
ı		ŢR				183 9 Q B
ı	2. Property Controlling S	TR				記録える 副
ı	in Section S3. Miscellaneous S	TR				382 883 883 883 883 883 883 883 883 883
ı	Property in Sec.	TR				S C C C
ł	· · · · · · · · · · · · · · · · · · ·	'K			D.	
ı	4. Lot No. Recorded Black			į.		gister of Deeds Stamp & File Number
ı	4. Lot No, Recorded Plat _ 5. Private Claims			···		
ł					1 7	3 C D E F G H I J K L
ı					2 }— }	;
ı	I, William Lenca, in a field requirements of P.A. 74, Michigan P.A. of 197	survey on Ton	100	-6. (3	
ł						9 10 11 12
ſ						
	that the corner points mentioned in lines 3, 4 a Board of Land Surveyors or by a Decree of recovered, found as expressed below:	nd 5 above were in o	onformance wit	h the rules of the Michiga	r 6 -18	17 16 15 14 13
	recovered, found as expressed below:	a comit of fam, 6	istablished, re-c	established, monumented	, '	+++++++++++++++++++++++++++++++++++++++
	NOTE: Not more than 2 comers, all in the on this certificate.	Same fown and m	700 march	_	8 -19	20 21 22 23 24
	on this certificate.	amina tomi alia ia	nge, may be re	corded	9	
					10 30	29 28 27 26 25
					11	
	A. Description of original manuscript				12 31-	32 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:						
1852: Original Survey by Francis Coleman - B.T.'s - Beech, 12" - N76°E - 39 lks; Beech, 12" - S60°W - 59 lks. All original evidence for this corner has been destroyed by county road improvements.						
	evidence for this corner has	been destroyed b	y county road	improvements.	ecn, 12" - S	60°W - 59 lks. All original
	B. Description of corner evidence found at	1d/or method anni	بينياليما			
	After a caroful mount . C.:	.a.o. meatod app	ned in restoring	g or reestablishing corr	ier:	
	After a careful search of the corner are restoration. We therefore set the corn	ea, we found no	widence of th	e original corner acco	essories, or	evidence of subsequent
	running North. This position lines up	reith the 357-e Y	ne of an East	- West County Road	and in line	with an ancient fence line
	evidence of the position of the original	corner.	mo or a cat-o	ver area to the South,	and is acco	pted as the best available
		-				
C	Description of monument for corner and a	CCESSOries establi	ioboet en u			
	Set 5/9" = 74" Tan D. 1/2 4 4 5	and and the search	siled to perpe	tuate locating the posit	tion of the c	orner:
	Set 5/8" x 24" Iron Rod/3-1/4" dia. Alu	m. cap stamped:	for corner loc	ation in Monument B	ox;	A WRENAM
	7" dia. Oak	****	55.47 feet	•		# LENCA + LAND
	20" dia. Norway Pine		102.46 feet	Scr. NBT Scr. NBT		SERVEYOR S
	8" dia. Maple 6" dia. Oak	S390W 6	59.95 feet	Scr. NBT		
	Metal Survey Sign Post		5.33 feet	Scr. NBT		
		•	1.6 feet			AND THE
NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.						
Sic	aned by William Force			unit succe capt. D	asiances to	trees are to nail in side of tree.
	The state of the			Date Se	p. 27, 1999	ı
Ju	rveyor's Michigan License No	6461				