## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in		raing n	equire	ment of Act 14,	WITCH. F.	M. 1570	•									
	Menomi nee	(	Located In:		Corner Code	<b>#</b> #											
1.	Public Land Survey		T 37N R 2 T R T		E-3.												
2.	Property Controlling in Section		T R T R _														
3.	Miscellaneous Property in Sec.	S	T R				Re	giste	er of	Dec	eds S	itam	p &	File	Nun	nber	
4.	Lot No, I	Recorded P	lat		<del></del>	<del> </del>		_	A R	c	ħ	E F	: G	н	1 3	ĸ	
<b>5</b> .	Private Claims							-	ΪŢ	Ť	Ť	П	Ť	Ϋ́	П	Ť	Ť
								3	l 6	1	- 5 — 	l i	1	- 3	2	1	-   -
	David B. Babbitt	in a field	survey on	6/	22	. 19 87		4				9	_	-10-		1——	-12
do in	hereby certify that under re lines 1 and 2 above were i	quirements o n conforman	IP.A. 74, Michig ce with regulati	an P.A. o ions and	f 1970, the corner po rules therefore as	oints mention required in	i the	6 7	[- 'i°	$\frac{1}{1}$	-17— -	 		-15	!	<b>-</b>	- 13- 
Ma abi	rrent manual of survey instr nagement or by a decree of ove were in conformance w	a Court of La	w and/or that the of the Michigan I	e corner Board of	points mentioned in Land Surveyors or t	llines 3, 4 a by a Decree	ind 5 e of a	8	— 19 — 1		-20	21			2:	9	-24-
expressed below:			shed, monumented, re-monumented, recovered, found as					10	  30	$\perp$	-29	28	,	-27—		; <b> </b> -	-25-
NC	OTE: Not more than 4 or this certificate.	•	in the same to	own and	i range, may be r	ecorded		11 12 13	-31	+	-32	33	)	-34	-3!	5	-36-
A.	Description of original	monument	and accessori	ies and/	or subsequent re	storation:		13	<b></b>		•		•	-			
	E-3. NE section	corner	of Section	8. '	Wood post.	Hemlock DO	( 10" 10"										

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

  E-3. I set this corner from the nearest feature calls (foot of hill I chain east and summit of hill 3 chains south) and with knowledge of measurements to meander corner west 1/4 cor. south 1/2 mile 1/4 cor. east 1-1/2 miles and the occupied position for the township line north. This position is near record south to the 1/4 cor. common to Sections 8 & 9. It also fits calls for enter and leave tam. swamp. 20.00 chains and 22.00 chains south, and it fits a call for enter cedar swamp 24.00 chains north. There is, however, a shortage of about 250' between this corner position and the occupied township line north. From evaluating all of the feature calls along the line between Sections 4 & 5, it appears that there was a chainage error in the vicinity of the 1/4 cor. The original survey of this twp. was done by James Mullet and wherever I have worked in his surveys, I have found his measurements and bearings to be erratic. William Burt's examination of the line between Sections 28 & 29 of this twp. finds the line to be 1.50 chains longer than James Mullet's record, which is proof that Mr. Mullet's measurements were not accurate. A proportionate position for this corner would not fit the feature calls at all. 1, therefore, believe this method restores the corner closer to its
  - E-3. DNR Monument.
    6" spruce S8E, 4.6'
    5" spruce N80E, 37.8'
    5" spruce S69W, 28.9'
    6" spruce N25W, 93.7'
    £ 0F NW-SE trail road West 19'

tion than any other method I could use.

Signed by Harif	B. Baffitt	Dale 12-3-87	
Surveyor's Michigan License No	21558	TARM AMERICA BY MIRWAY STATE AT LANG SHEVENAS IN	v 20 (A)

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983