SURVEY & REMONUMENTATION

FEB 1 1 1998

SECTION LAND CORNER RECORDATION CERTIFICATE

IOM	Filing		it of Act 74, M	ich. P.A. 19	70			Contract and	-			
For corners in		,		1				,				
MENOMINEE	Located In:	Corner Co	do#				يا شئلسين	17. j 100	<u>~</u>			
(County)	Located III.	Contrar Co	ue #				116	ipoi Jaan	35	KOTELIO		
(,/								زني	400	#11 []]]		
1, Public Land Survey	T38N_R_	27W	I_3	1				ن خ	2			
	<u>TR</u> _						100	,	40.75	553		
	ŢR.						1, 1, 1	(b)		50 P		
2. Property Controlling	s '''-						7.00	300	Ü	- <u>-</u>		
in Section	S T R						₩°'£	اند		t · ·		
3. Miscellaneous	S T R						•	•	CO			
Property in Sec.	S TR_				Dag	detor e	f Deec	in Cin	mn £	Cile 1	dund	or
				<u> </u>	reg	ister (I Deec	15 316	iiip a	- HC I	407110	
4, Lot No, Reco	rded Plat				, A B	С	D E	F G	H	ı j	к	L
5. Private Claims				-	, [T	\prod	T	\Box		Ţ
					2 6	_	5	1-1	-3-	2 - 	-	1-
					3			╁╌┼	-	P -		╁
William Lenca	, in a field survey on _	Aug. 11 , 19	97 do hereby st	ate that under	4 ₹		þ	9	-1¦0-	1 l-		1,2-
requirements of P.A. 74. Michia	an P.A. of 1970, the corne	r points mentioned	d in lines 1 and 2 a	bove were in	5		<u> </u>	 				1
conformance with regulations and United States Department of the	d rules therefore as required interior. Bureau of Land Ma	in the current ma engrement or by a	nual of survey instrudence of a Court of	uctions of the	6 -1			16	_ _	14		 13-
hat the corner points mentioned	d in lines 3, 4 and 5 above v	vera in conforman	ce with the rules of	the Michigan	7	'		ĨĹ	_ Ï	Ш		Ĺ
Board of Land Surveyors or b		Law; established	i, re-established, i	monumented,][]				Ţ
recovered, found as expressed b	elow;				819	<u></u>	[21	22 	23.	- -	74-
NOTE. Not more than 2 cor	ners, all in the same town	and range, may	be recorded		9	_	 	 -	- -		-	┪
on this certificate.	·				1030		9	28	_27	26		2′5⊷ I
					11							╀
					12 31	.—:	32	33	_34	35] 36-
	,				13							1
cvidence for thi 1976: CERTIFIED SU shows ties to of 1987: L.C.R.C. No. 7-	onument and accessore by Harvey Mellen - I s corner has been destr JRVEY No. 114 by Ro ther property corners in 49 by William Lenca, I ; 1" dia. Iron Pipe - Ni	B.T.'s - Hemlox coyed by loggin bert Perkins, R the area. RLS No. 26461	ck, 18" - N53.5 ⁰ g activictics. LS No. 12027, o , erroncously us	E - 47 lks.; (describes this cs a 1-1/2" d	s corner a	ns an i	ron bol	lt in 4'	" casii	ng an	d	
B. Description of corner evi	:	thed emplied in	ootaring or road	abliching car								
B. Description of corner evi	idence found and/of me	ttiod applied iti i	estoring or recei	abiisinig con	ilei.							
In a 1987 survey of Secti recorded it in L.C.R.C. 1 (Certified Survey No. 11 survey. This monument Lumber Company. The contained in Certified su position of the original c	No. 749. In surveying to the found a 1-1/4 in matches with on found iron bolt and casing harvey No. 114 and Certi	the Hermansvil ich square head I at the North C ive since been d	le Industrial Sit I iron bolt in a 4 Quarter Corner o lestroyed, howe	e in 1991, we inch iron ca of Section 11, wer we replace	e retraced using mains, having and the co	i Robo Iching been p orner p	ert Perk ties to laced l osition	cins 19 other by Wis n from	976 St corne sconsi infor	urvey ers in in Lad matic	this nd & on	
C. Description of monument Sct 3/4" dia. x 4' long als					sition of t	ne cor	ner:					
7" dia. Cherry		S590W	50.00 feet	Scr. NBT								
1" dia. Iron Pipe		N180W	32.51fcet	001.17111								
1" dia. Iron Pipe		North	84,63 feet									
Power Pole		S80°E	161.75 feet									
Metal Survey Sign Po	ost	North	4.1 feet									

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Surveyor's Michigan License No._