SURVEY & REMONUMENTATION

APR 2 4 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by	Menominee County
Peer Group	Remonumentation Under Act 345 Of

PA 01 1990 On 2 9 199 94

Fo	or corners in MENOMINEE	Located In:	Corner	Code <i>≠</i> ≠					0 > 2	42	22. 22.		
1.	(County) Public Land Survey	T <u>39 N</u> R25 W	5 W (J-5)&	J-5 & K-5				RBARA FEGISTER	F# 14 6	DEC 27	RECEIVED FI		
		T R _ T R _					;	POHA Services	D. D.	受	FOR RECORD		
2.	Property Controlling in Section	S T R _ S T R _									2		
3.		S T R _			Re	egister	of De	∠ eds Si	tamp	் & File	e Num	ber	
	Property in Sec.	S T R _		·L								-	
4.	Lot No.	, Recorded Plat					вс		: : e:			v	
5.	Private Claims	J-5 [S1/4 COR SEC 11] K-				_ ^		0 6		G H	\dashv \dashv	``	┱┑
	·	J-5 [S1/4 COR SEC 11] K-	-5 [SE COR. SEC 11]			2 _	6	- 5-	4	- 3-			-{{
						3	++	+-+	_	++	+-+		+1
	M.P. DAVIS	, in a field survey on	OCTOBER	10 94		4	- 7	- 8	-9- 	10	1	+	-12
in cu	hereby certify that under lines 1 and 2 above were rrent-manual of survey in	requirements of P.A. 74, Michige in conformance with regular structions of the United States of a Court of Law and/or that the	gan P.A. of 1970, the co dions and rules there is Department of the fi	orner points mention fore as required in Interior, Bureau of I	ioned in the Land	6	18	17-	16	15	14		-13-
ab Co	ove were in conformance ourt of Law; established	with the rules of the Michigan d, re-established, monument	Board of Land Survey	ors or by a Decree	e of a	9	Ĭ	1					
	pressed below:					1	30	-29	—28 	1-27-	26	+	-25
NC	OTE: Not more than 4 on this certifica	4 corners, all in the same to te.	lown and range, ma	y be recorded		11	31	-32-	33	34	35	+	36
		nal monument and accessor . ADAIR D.S 1852 - WOOD											

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-5 [SE COR S.11] G. ADAIR D.S.-1852-WOOD POST (CEDAR 10"-N74°E-0.17 CHAINS) (CEDAR 16"-S80"W-0.18 CHAINS)

NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION.

NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION.

- J-5 [S1/4 COR S.11] NO CORNER EVIDENCE FOUND AS ALL EVIDENCE OF CORNER POSITION APPEARS TO HAVE BEEN DESTROYED DURING ROAD CONSTRUCTION. RESET S1/4 CORNER ON A STRAIGHT LINE BETWEEN SECTION CORNERS E. & W. & IN LINE WITH AN ANCIENT FARM FENCE TO SOUTH & OCCUPATION LINE TO NORTH.

 ACCEPTED THIS LOCATION AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.
- K-5 [SE COR S.11] NO CORNER EVIDENCE FOUND AS ALL EVIDENCE OF CORNER POSTION APPEARS TO HAVE BEEN DESTROYED DURING ROAD CONSTRUCTION. RESET SE CORNER AT APPROX C/L INTERSECTION OF COUNTY ROADS E, W, & S. & IN LINE WITH AN ANCIENT FARM FENCE TO NORTH. ACCEPTED THIS LOCATION AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.



BEVISED JAN., 1983

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - J-5 SET A BERNTSEN AINB30 ALUMN MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

 IRONWOOD 5"
 IRONWOOD 6"
 SURVEY MONUMENT SIGN POST
 MAPLE 15"
 C/L E & W CO. RD.

 572°E
 \$10°E
 N34°W
 \$35°W
 NORTH

 55,76'
 67.32'
 22.60' (TO FACE)
 72.93'
 2.60'

K-5 SET A BERNTSEN AINB30 ALUMN MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

TAMARACK 9* POWER POLE C/L E & W CO. RD. SURVEY MONUMENT SIGH POST S41°W S42°E NORTH NORTH 60.76' 49.10'(TO FACE) 0.70' 14.16' (TO FACE)