Approved by Menominee
Land Survey Remonumentation
Pear Group Under Act 345 Of

PA 0 1990 On DET. 20 199 =

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Manandana			do -++				3			
Menominee Locate	ed In:	Corner Co	ue			ಗಾಜಾಗಿ	<u>ک</u> روز ک	တ်		
(County)			1			13.636	$\tilde{\sigma}_{ijk}^{ret}$:	<u></u>	=======================================	
1 Dublic Land Current T	HM D 24W	L5					š (L. 1	-	<=	
·	11N R 26W	15/(A5 T	41 02511)		1 (22)	. ~	ረ ነ		
	11N R _26M_		4110 KES VO)	,		- 1217	∵~0		ā	
	<u>R</u>						· (x -		 .,	
	R		1							
Property Controlling S T							3-6	ز لوبوا 	·i	
in Section S T						الله الله	= (ပၢ သ		
	R			Regist	ter of D	eeds S	tamp 8	File	Vumbe	r
Property in Sec. S T	R		\			<i>_</i>				
•										
Lot No, Recorded Plat					А В	CDI	E F G	a H	JK	L
. Private Claims					2 _ 6_					
	ar in that also with a second				ľ	┯┋═┋	-1-	— 3 —	2	-1
SCANPLE OS 47-05 THIN,	R2562 V	•		;	3	 	1-1	_		-
·	M5 Febru	ary 07, 1995		•	⁴ 	╁╌┇╌┤	9	—1¦0	1 1	— ļ2
Paul R. Bressette , in a field survey					5	1-1-1				
lo hereby certify that under requirements of P.A. 7					6 _ 18_	- -	 16	 15	 14	_ —13
n lines 1 and 2 above were in conformance with current manual of survey instructions of the Unite	•		•		7			Ī		L
Management or by a decree of a Court of Law and/					8 _ T			1		
bove were in conformance with the rules of the N				e of a		20-1	-21-	22 	23	24
Court of Law; established, re-established, mo				ıd as	°├─ ├ ─	1 1 1		- -		
expressed below:				11	0 —з¦о—	-29	<u>28</u>	—2 7 ~~	26	<u></u> 25
NOTE: Not more than 4 corners, all in the	same town and	range, may b	e recorded	1	¹┡ ┈ ┞┈	} 				\rightarrow
on this certificate.				13	2 31	32-	33	34	35	
•				1:	ـــــــا ه					
. Description of original monument and a	ccessories and/	or subsequent	t restoration	:						
(L5)Quarter corner common to Sections 12 at 18 M65M 9 links. 1963: Billy Buckler, RI a rotted cedar in position for second OBT vVol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1853 marked two additional witnesses: Hemlock 20	itnessed by: 9 3, 7 and 18. 1 2: E.C. Martin,	" Cedar S82E 846: Austin Bu DS. Closed on	10 links; 1 ert, DS. Set corner duri	il" Cedar M t cedar post ing subdivis:	witness ion of 1	sed by: 141N,R25	Hemloc W and	k 16 T41N,R	503E 2 26W and	:0 I
18 N65W 9 links. 1963: Billy Buckler, RI a rotted cedar in position for second OBT was vol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1857 marked two additional witnesses: Hemlock 20 1" iron pipe w/ brass cap from one hemlock place witnessed by: 9" Aspen S26W 49 links. Description of corner evidence found and (L5)Found wood post and NBT's as described Wood post was replaced with DNR monument (and faithful PERPETUATION of the position of (M5)Found monument and NBT (now 18" Aspen) overgrown. Monument was rewitnessed as for	sitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10: N48E 30 link 10: stump in proper 10: style style 10:	" Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. 8 position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume	10 links; 1 ort, DS. Set corner duri birch 20 S82 ee probable Corner is sing or reesta with both fa p), two more	t cedar post ing subdivis: 2W 41 links stump botton recorded in ablishing co aces open and e witnesses in	witnession of it (July), ms in pi Vol.2, rmer: d scribi	sed by: 141M,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever I Meno Measur I is ac	k 16 T41N,R Buckl al old ainee ing no cepted since	SOJE 2 26W and ar, RLS stakes County tch vis as a c	0 6. S in ible aref
18 N65M 9 links. 1963: Billy Buckler, RI a rotted cedar in position for second OBT v Vol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12,	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in excell 14 iron pipe w/ 15 iron pipe w/ 16 iron pipe w/ 16 iron pipe w/ 17 iron sacce 18 sugar 18 suga	" Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0' S48E 24.1' S47W 22.8' N64W 8.9' re blazed, scr A metal post to monument.	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign	t cedar post ing subdivis: 2W 41 links stump botton recorded in ablishing coaces open and witnesses withful PERPETITE ceding the perpet	witnession of (July), ms in p. Vol.2, erner: d scribalere mail	sed by: 141N,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever of Meno measur I is acc tree osition	k 16 T41N,R Buckl al old ainee ing no cepted since n of t	SOJE 226W and are, RLS stakes County tch vis as a county	o l i in ible are
18 N65W 9 links. 1963: Billy Buckler, Ria rotted cedar in position for second OBT was content of the county Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1852 marked two additional witnesses: Hemlock 20 1" iron pipe w/ brass cap from one hemlock place witnessed by: 9" Aspen S26W 49 links. Records cription of corner evidence found and CL5)Found wood post and N8T's as described whood post was replaced with DNR monument (M5)Found monument and N8T (now 18" Aspen) overgrown. Monument was rewitnessed as for corner. CL5) 1" iron pipe w/ 4" aluminum cap 7" Cedar N40E 18.2" (1/45,N8T) 11" Cedar S76E 6.5" (1/45,N8T) 11" Cedar S76E 6.5" (1/45,N8T) 13" Cedar N5W 21.8" (1/45,N8T) 141 N8T's are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in excell 14 iron pipe w/ 15 iron pipe w/ 16 iron pipe w/ 16 iron pipe w/ 17 iron sacce 18 sugar 18 suga	" Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0' S48E 24.1' S47W 22.8' N64W 8.9' re blazed, scr A metal post	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign	t cedar post ing subdivis: 2W 41 links stump botton recorded in ablishing coaces open and witnesses withful PERPETITE ceding the perpet	witnession of (July), ms in p. Vol.2, erner: d scribalere mail	sed by: 141N,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever of Meno measur I is acc tree osition	k 16 T41N, R Buckl al old ninee ing no cepted since n of t AUL F ESSETT LAND RVEYC No.	SOJE 226W and are, RLS stakes County tch vis as a county	o l i in ible are
18 M65W 9 links. 1963: Billy Buckler, Rice rotted cedar in position for second OBT was rotted cedar in position for second OBT was recorded. (M5)Section corner common to Sections 12, links; Hemlock 7 M63 1/2W 11 links. 1852 warked two additional witnesses: Hemlock 20 L" iron pipe w/ brass cap from one hemlock colace witnessed by: 9" Aspen S26W 49 links. Pescards ription of corner evidence found and CL5)Found wood post and M8T's as described whood post was replaced with DNR monument (M5)Found monument and M8T (now 18" Aspen) overgrown. Monument was rewitnessed as for corner. Description of monument for corner and corner. CL5) 1" iron pipe w/ 4" aluminum cap 7" Cedar N40E 18.2' (1/45, N8T) 11" Cedar S76E 6.5' (1/45, N8T) 11" Cedar S76E 6.5' (1/45, N8T) 13" Cedar S30W 16.7' (1/45, N8T) 13" Cedar N5W 21.8' (1/45, N8T) 1	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in excell 14 iron pipe w/ 15 iron pipe w/ 16 iron pipe w/ 16 iron pipe w/ 17 iron sacce 18 sugar 18 suga	"Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0' S48E 24.1' S47W 22.8' N64W 8.9' re blazed, scr A metal post to monument. notch in butt	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign	t cedar post ing subdivis: 2W 41 links stump botton recorded in ablishing coaces open and witnesses withful PERPETITE ceding the perpet	witnession of (July), ms in p. Vol.2, erner: d scribalere mail	sed by: 141N,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever of Meno measur I is acc tree osition	k 16 T41N, R Buckl al old ninee ing no cepted since n of t AUL F ESSETT LAND RVEYC No.	SOJE 226W and are, RLS stakes County tch vis as a county	o l i in ible are
18 N65W 9 links. 1963: Billy Buckler, Ria rotted cedar in position for second OBT wol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1852 marked two additional witnesses: Hemlock 20 1" iron pipe w/ brass cap from one hemlock place witnessed by: 9" Aspen S26W 49 links. Description of corner evidence found and (L5)Found wood post and NBT's as described. Wood post was replaced with DNR monument (M5)Found monument and NBT (now 18" Aspen) overgrown. Monument was rewitnessed as for corner. Description of monument for corner and corner. (L5) 1" iron pipe w/ 4" aluminum cap 7" Cedar N40E 18.2" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 11" Cedar S30W 16.7" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 141 NBT's are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are measured to notch in butt blaze, bearings are magnetic.	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in proper 14 iron pipe w/ 15 iron pipe w/ 16 the original 17 sayar 18 sayar 18 sugar 18	"Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0" S48E 24.1" S47W 22.8" N64W 8.9" re blazed, scr A metal post to monument. notch in butt e magnetic.	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ent. Distance ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign was blaze,	t cedar post ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis stump botton recorded in ablishing co aces open and witnesses the subdivines ce is measure the perpett	witnession of (July), ms in pivol.2, mner: d scribinere man	sed by: 141N,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever of Meno measur I is acc tree osition	k 16 T41N, R Buckl al old ninee ing no cepted since n of t AUL F ESSETT LAND RVEYC No.	SOJE 226W and are, RLS stakes County tch vis as a county	o l i in ible are
18 N65W 9 links. 1963: Billy Buckler, Ria rotted cedar in position for second OBT wol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1852 marked two additional witnesses: Hemlock 20 1" iron pipe w/ brass cap from one hemlock place witnessed by: 9" Aspen S26W 49 links. Description of corner evidence found and (L5)Found wood post and NBT's as described whood post was replaced with DNR monument (M5)Found monument and NBT (now 18" Aspen) overgrown. Monument was rewitnessed as for corner. (L5) 1" iron pipe w/ 4" aluminum cap 7" Cedar N40E 18.2" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 15" Cedar N5W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 15" are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are measured to notch in butt blaze, bearings are magnetic.	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in proper 14 iron pipe w/ 15 iron pipe w/ 16 iron pipe w/ 17 iron pipe w/ 18	"Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0" S48E 24.1" S47W 22.8" N64W 8.9" re blazed, scr A metal post to monument. notch in butt e magnetic.	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign	t cedar post ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis stump botton recorded in ablishing co aces open and witnesses the subdivines ce is measure the perpett	witnession of (July), ms in pivol.2, mner: d scribinere man	sed by: 141N,R25 . 1955: lace and p.204 o ing and rked and	Hemloc W and Billy I sever of Meno measur I is acc tree osition	k 16 T41N, R Buckl al old ninee ing no cepted since n of t AUL F ESSETT LAND RVEYC No.	SOJE 226W and are, RLS stakes County tch vis as a county	0 6. S in ible aref
18 N65W 9 links. 1963; Billy Buckler, RI a rotted cedar in position for second OBT was vol.2, p.358 of Menominee County Records. (M5)Section corner common to Sections 12, links; Hemlock 7 N63 1/2W 11 links. 1855; marked two additional witnesses: Hemlock 20 1" iron pipe w/ brass cap from one hemlock place witnessed by: 9" Aspen S26W 49 linker Description of corner evidence found are (L5)Found wood post and NBT's as described whood post was replaced with DNR monument (2 and faithful PERPETUATION of the position of (M5)Found monument and NBT (now 18" Aspen) overgrown. Monument was rewitnessed as for corner. CL5) 1" iron pipe w/ 4" aluminum cap 7" Cedar N40E 18.2" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 11" Cedar S76E 6.5" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) 13" Cedar N75W 21.8" (1/45,NBT) NBT's are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are measured to notch in butt blaze, bearings are magnetic.	aitnessed by: 9 13, 7 and 18. 1 2: E.C. Martin, 10 N48E 30 link 11 stump in proper 12 stump in proper 13 stump in proper 14 iron pipe w/ 15 iron pipe w/ 16 the original 17 sayar 18 sayar 18 sugar 18	"Cedar S82E 846: Austin Bu DS. Closed on s (June); Y. B position, thr 04W 40 links. plied in restor ent condition 4" aluminum ca corner. et from monume pted as a care tablished to p n pipe w/ bras N17E 23.0" S48E 24.1" S47W 22.8" N64W 8.9" re blazed, scr A metal post to monument. notch in butt e magnetic.	ort, DS. Set corner duri tirch 20 S82 ee probable Corner is ing or reesta with both famp), two more ent. Distance ful and fait erpetuate loss cap (S.7,NBT) (S.13,NBT) (S.12,NBT) ibed, painte with sign was blaze,	t cedar post ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis ing subdivis stump botton recorded in ablishing co aces open and witnesses the subdivines ce is measure the perpett	witnession of (July) ms in pi Vol.2, rner: d scribi were mail ed to co UATION (sed by: 141N,R25 . 1955: lace and p.204 of ing and rked and enter of of the p	Hemloc W and Billy sever of Meno Reasur is acc tree osition	k 16 T41N,R Buckl al old ainee ing no cepted since n of t AUL F ESSETT LAND RVEYC No. 37270	SOJE 226W and and a stakes County tch vis as a stake original to the county tch vis as a stake original tch vis as	in sible are final