MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was replaced from down wood post which was in proper position with Y. Birch stump badly rotted. (Y. Birch 16" N 67° W 05 links) and Cedar butted, faces visible, (Cedar 12" S 62° E 08 links).

No iron marks visible.

SURVEYOR'S SEAL

SIGNED Suckey DATE 8-22-63

REGISTERED LAND SURVEYOR
Billy D. Buckler