SECTION

Signed by

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1220

For o	corners	s in		i imig rioquii	cincin of Act 14, micri. 1.	1. 1370	74/3	38		
N	1issau	ikee Coi	unty	Located In:	Corner Code #					
1. P	ublic I	Land Su	ırvey	T_22N_R_05W T R T R	B-13	PECORDED	MISSAUKEE COUNTY MICHIGAN TECORDED DEC 0 9 1999 42m.			
ir 3. N	Sect liscell	y Contr ion aneous ty in Sed	S S	TR TR TR TR TR			0	Flore REGISTER np & File Number		
4. L	ot No.	·	, Recorded	l Plat						
		Claims				A B C	D E F G	Н І	J K L	
requirements were instrudecre confo	rements in conf ctions e of a (rmance	s of P.A. formance of the Ur Court of Le with the	74, Michigan P.A. with regulations a nited States Depa aw and /or that t e rules of the Mic	of 1970, the corner point and rules therefore as requ artment of the Interior, Bu he corner points mentione	9 99 do hereby state that ur ts mentioned in lines 1 and 2 ab ired in the current manual of sur reau of Land Management or bid in lines 3, 4 and 5 above wereyors or by a Decree of a Cour as expressed below:	vey 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	8 — 9 — 17 — 16 — 120 — 21	15	-1415	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.						9	20 21		23 24	
						10 30	29——28——	2 7	-2625	
Α. [Descrip	tion of o	original monume	ent and accessories and	or subsequent restoration:	11	3233	34	3536	
E	3-13)	1837		Section Post by John B ISE-40 lks, 16" Hemloo		13				
E	3-13)	1907			R5W: no information shown	for				
E	3-13)	1912	Beuthien Survey; 4" Maple-S55E-81 lks, Telephone pole- N29E-32 lks.							
	3-13) 3-13)	1938 1977	38 Schaaf notes: Found corner in Road.							
E	3-13) 3-13)	1977 1977	Cavanagh Sur Cavanagh LCI Stop sign-SE-	vey, S-1, Page 359: S RC, Liber 1, Page 543: 47.2'.	et 1/2" steel bar. Set 1/2" steel bar, Fence po		•			
6	3-13)	1986	Cavanagh LCF Stop sign-SE-		t 1/2" steel bar, Fence post-l	N30W-27.85', Map	le-SW-35.7	· ,		
E	3-13	1998	, v							
В. С	escrip	tion of c	orner evidence	found and/or method a	pplied in restoring or reestab	lishing corner:				
	:-13)	Quarter section corner common to Section 31, T22N, R5W and Section 1, T21N, R5W. Found 1/2" iron as recorded in Liber 1, Page 543. Corner is ± 2 ' north of centerline east-west and 14.5' east of fenceline north. This corner was not accepted at this time due to discrepancies with recorded and physical evidence. Established corner based on old fence lin to North which agrees with prorated distances to 1912 Beuthien survey and split of Right-of-Way fences on North and South side of East-West road. Corner is in centerline of East-West road and ± 10 ' West of Centerline Road to South. This corner is accepted as the best available evidence of the position of the original corner.								
C. D	escrip	tion of n	nonument for co	orner and accessories e	stablished to perpetuate loca	ting the position of	the corner:	:		
В	-13)	Set ½" NO7E S29E S48W S50W East	x18" rebar and 33.85' 91.14' 59.94' 45.24' 14.35'	Found D.H. nail in wes Set nail over bent D.H Set nail in corner fence Found iron **The Control of the Control	t face of telephone riser pole st face of 40" twin maple. . nail in power pole.	Peer Group Revi	ewed and A	.pprovec	i 	
Signe	d hv	(70.	S PROP	EERS * * * * * * * * * * * * * * * * * * *	J. Dean Geers, Missa		esentativo	 e	
_		Michigan	License No. 33	977	ESSION Dat	e <u>//-23-99</u>				