SURVEY &

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGOLGOUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

Newaygo (County)	Located in:	Corner Code#	OJ	O. waas das das das das das das das das das	n. Brown
Public Land Survey Property Controlling in Section Miscellaneous	T 12N R 14W T R T R T R S T R	C-6	VOL. 1	PAGE	232
Property in Sec.	S T R	<u></u>			
	·	Regi	ster of Deeds St	amp & File	Number
4. Lot No, Reco	ded Plat	•	A B C t	EFG	II I J K L M
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curred bepartment of the Interior, Burea Law and/or that the corner point conformance with the rules of Decree of a Court of Law; establic recovered, found as expressed be Note: Not more than 4 cornered on this cornered on this cornered.	in a field survey on October 3 irements of P. A. 74, Michigan P.A. of above were in conformance with regular to manual of survey instructions of the Grand Management or by a decreate mentioned in lines 3, 4 and 5 at the Michigan Board of Land Survey shed, re-established, monumented, relow: Corners, all in the same town ertificate.	1970, the corner ations and rules to United States ee of a Court of above were in eyors or by a e-monumented,	12 -31 - 32		
vvest One Quarter Comer	, Section 17, Sheridan Townsl	nip, Newaygo County, Mid	chigan	<u> </u>	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John H. Mullett 1838 10" Black Ash S36°W 11 Links (7.26)#1 6" Black Ash N67°E 19 Links (12.54)#2

Douglas W. Bonnema R.L.S. #12579 Found 1" Iron November 9, 1976 12" Maple Southeast 54.37' #5 Fence Post Northeast 42.25' #4 36" Maple North Northwest 43.28' #6 Patrick A. Salisbury R.L.S. #13594
Set 1" Pipe ±24" long half way and on line between the
Northwest and Southwest Section Corners. February 6, 1975
28" Maple S63°W 48.87' #3
Wood Corner Fence Post N40°E 42.34' #4
10" Maple S45°E 54.14' #5
30" Maple N27°W 43.53' #6

William Fries, Jr. R.L.S. #30389
January 20, 1986 LCRC #708
Found 1½" Outside diameter pipe which fits record accessories. Pipe was bent so I reset it with ½" Iron and cap 14"-14" Twin Red Maple N69°E 35.05' #7
15" Red Maple S48°E 54.32' #5
35" Red Maple S61°W 48.92' #3
12" Red Maple N88°W 26.65' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" Rod and cap #30389 in centerline of road going South and the centerline of road going North is 6 feet East and the centerline of road going East is 3 ft North and the condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 (fallen), #5 thru #7 good condition, #8 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

THE SORMER,	
Removed ½" Rod and cap #30389 and set a 4" diameter Harrison cast iron monur substantial marker for the section corner and is accepted as a careful and faithful re	Control of the onginal corner
20 Maple S63°W 48.92' Set spike with tag over existing spike in Northwest side of 10" Maple S45°E 54.71' Found spike in Southwest side of tree. #5 36" Maple N27°W 43.21' Found spike in Southwest side of tree. #6 14"-14" Twin Red Maple N69°E 35.18' Spike in Southeast side of tree. #7 14" Maple N75°W 27.34' Tree has been previously blazed. Signed by Norman L. Ochs Surveyor's Michigan License No. 2004.	NORMAN L. OCHS LAND SURVEYOR OVER 17, 1996 Mo. 22439 by Michigan State Board of Land Surveyor, surveyo
111 A. G.	· · · · · · · · · · · · · · · · · · ·