

MAR 02 1999

NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE 9 FEB 17 PM 3 39 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

SECTION

For corners in Newaygo	Located in:	Corner Code#	Linsa M. B.	www.
(County) 1. Public Land Survey 2. Property Controlling	T <u>13N</u> R <u>11W</u> T R T R T R S T R	B-1	VOL. 2	232
in Section 3. Miscellaneous Property in Sec.	STR STR STR		Register of Deeds Stamp & File	Number
4. Lot No. , Reco	orded Plat		1 C D E F G H	I J K L M
therefore as required in the cur Department of the Interior, Burn Law and/or that the corner p conformance with the rules o	, in a field survey onOctober 22_ uirements of P. A. 74, Michigan P.A. of 2 above were in conformance with regrent manual of survey instructions of the sau of Land Management or by a depoints mentioned in lines 3, 4 and 5 of the Michigan Board of Land Sublished, re-established, monumented	ulations and rules the United States of above were in urvevors or by a	3 4 - 7 - 8 - 9 - 10 5 - 18 - 17 - 16 - 15 7 - 19 - 20 - 21 - 22	1111
recovered, found as expressed	^{pelow:} corners, all in the same tow	·	9 10 30 - 29 - 28 - 27 11	- 26 - 25 -
North One Quarter Corner,	Section 6, Big Prairie Township, N	Newaygo County, Michigan	12 31 32 33 34	† 35 † 36 †

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Not set.

Lionel Roy Emery R.L.S. #24593
May 29, 1981 LCRC #527
Found ½" Iron Rod with plastic cap (illegible)
Concrete Monument N30°E 37.44' #1
½" Iron Rod East 17.48' #2
10" Poplar S55°E 52.46' #3
12" Poplar S08°E 25.05' #4

Norman L. Ochs R.L.S. #22439
Drawing Number 98082AC April 29, 1998
Found ½" Rod and cap (illegible)
6" Maple N03°W 41.25' #5
12" Red Oak S19°W 47.30' #6
Power Pole S60°E 77.50' #7
4" Concrete Monument N30°E 37.40' #1

NORMAN L: OCHS

ED LAND

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" X 18" Rerod and the centerline of the East and West bituminous road is 1 foot North and the centerline of the two-track going South is 14 feet ± West. The condition of the recorded witnesses are: #1 and #2 good condition, #3 and #4 gone, #5 thru #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod and set a 23/4" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful establishment of the best available position of the corner.

3" diameter Concrete Monument with 1/2" Rerod N25°E 37.5	O' #1
South One Quarter Corner, Section 31, T14N R11W, East 1	7 45' #2
6" Maple N08°W 41.26' Found spike with tag #22439 in Eas	terly side of tree #5
14" Red Oak (blazed) S15°W 47.27' Found spike with tag #	22439 in West side of tree #6
Power Pole S64°E 77.68' Found spike with tag #22439 in No	ortheasterly side of note #7
\mathcal{N}	
Signed by 100 man T. Ocho	Date November 3, 1998
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group onDecember 8, 1998	Revised May 14, 1975 Revised Jan., 1983
Norman L, Schs, County Representative.	Trevised dalls, 1905
N. L. O.	NORMAN ***