SUMMER REMONUMEN

1996 Newaygo County Remonumentation Project

REGISTER OF DEEDS LINDA M. BROWNEWA

NEWAYCO COUNTY

COMMISSION

MAY 2.8 1997

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

REGIST '97 FEB 12

Newaygo (County)	Located in:	Corner Code#	C	Guida.	M. Sinds
Public Land Survey	· T <u>13N</u> R <u>12W</u> T R T R	<u>B-1</u>	vol. 1	PAGE	239
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR STR	Reg	ister of Deeds Sta	amp & File	Number
4. Lot No, Records. 5. Private Claims I, Norman L. Ochs do hereby certify that under requirements mentioned in lines 1 and 2 therefore as required in the currence of the Interior, Burre Law and/or that the corner poconformance with the rules of	in a field survey on <u>December</u> direments of P. A. 74, Michigan P 2 above were in conformance with ent manual of survey instructions au of Land Management or by a hints mentioned in lines 3, 4 ar the Michigan Board of Land dished, re-established, monumer	.A. of 1970, the corner regulations and rules of the United States a decree of a Court of nd 5 above were in Surveyors or by a	□		0
Note: Not more than 4 recorded on this		town and range, may be	!!		- - - - -

North One Quarter Comer, Section 6, Wilcox Township, Newaygo County, Michigan (city of White Cloud) A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Did not set corner

Ralph A. Smith R.L.S. #3421 Book 98 Page 51 1938 34" Gas Pipe 6" White Oak S05°±E 32.3' #1 14" White Oak S50°±W 63.5' #2

Patrick A. Salisbury R.L.S. #13594 Found 3/" Pipe February 26, 1975 12" Black Oak S83°E 6.65' #4 12" White Oak S04°E 32.69' #1 14" White Oak S56°W 64.31' #2 24" Black Oak N32°W 29.2' #3 Concrete Corner Fence Post South 36.27' Face. #5 Raiph A. Smith R.L.S. #3421 Book 68 Page 99 September 16, 1953 Found %" Gas Pipe 10" White Oak S05°±E 32.0' #1 20" Red Oak N35°±W 28.2' #3

Ralph A. Smith R.L.S. #3421 1962 Book 68B Page 17 Book 98 Page 51 Found %" Pipe 6" White Oak S05°E 32.3'#1 14" White Oak S50°W 63.5' #2 22" Black Oak N30°W 28.1' #3 10" Oak East 5.9' #4 Concrete Corner Fence Post S05°W 36.3' #5 South One Quarter Corner, Section 31, T14N R12W 9.57 #6

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" X 33" Iron Pipe and 1 piece of broken glass and the centerline of the East and West trail road is 15 feet South and the centerline of the gravel road going West is 4 feet South and the centerline of the gravel road going South is 24 feet West and the condition of the recorded witnesses are: #1 thru #6 good condition. Note: This position is within 1.5' of a G.L.O. prorated position.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/4" X 33" Iron Pipe with broken glass and set a 4" diameter Harrison cast from monthless 2000 and substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and is accepted as a careful and faithful reestablishment of the original corner and or the original corner and the faithful reestablishment of the original corner and or the original corner and o Removed 3/" X 33" Iron Pipe with broken glass and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as OF MICHIG

18" White Oak South 32.60' Found spike in West side of tree. #1 22" White Oak S57°W 64.35' Found spike with tag in Northwest side of tree. #2 34" Black Oak N28°W 29.18' Found spike in Southwest side of tree. #3 14" Black Oak S77°E 6.57' Found spike in North side of tree. #4 Metal fence post S12°W 34.35' #5 South One Quarter Corner, Section 31, Wilcox Township (Harrison Monument) East 9.54' #6

22439

LAND SURVEYOR 22439 PED LAND

16"-14" Twin Black Oak N23°E 32.70' Found spike in West side of tree. 110ma December 20, 1996 Date Norman L. Ochs

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Approved by Peer Review Group On ___December 23, 1996 Norman L. Ochs, County Representative.

Revised Jan., 1983

NORMAN

L. OCHS

Surveyor's Michigan License No.

A. Description (cont.)

Newaygo Engineering and Survey Company LCRC #1231 October 4, 1994 Found ¾" Pipe 15" Black Oak S83°E 6.56' #4 12" White Oak S04°E 32.61' #1 16" White Oak S56°W 64.27' #2 26" Black Oak N32°W 29.20' #3 South One Quarter Corner, Section 31, Wilcox Township East 9.53' #6