SHINEY-8-REMONUMENTATION

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 38

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

D אמעל

40 CN		,		
For corres FICTION Newaygo (County)	Located in:	Corner Code#	Lind	w M. Bra
1. Public Land Survey	T <u>13N</u> R <u>13W</u> T R T R	<u> -1</u>	VOL. 2	21
Property Controlling in Section Miscellaneous Property in Sec.	STR STR			
•	S		Register of Deeds Stamp & File	Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curropartment of the interior, Bured Law and/or that the corner po conformance with the rules of Decree of a Court of Law; establing recovered, found as expressed by		70, the corner ons and rules United States of a Court of one were in ors or by a monumented,	A B C D E F G H 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9	14 - 13 -
Note: Not more than 4 c recorded on this c	orners, all in the same town ar ertificate.	nd range, may be	10 30 + 29 + 28 + 27 +	26 - 25 -
Northwest Corner, Section 2,	Sherman Township, Newaygo Cour	nty, Michigan.	12 31 + 32 + 33 + 34 +	35 + 36 -
A. DESCRIPTION OF OR	RIGINAL MONUMENT AND ACC	ESSORIES AND	OR SUBSEQUENT RESTORA	TION:

G.L.O. Mullett and Brookfield 1838 18" Pine S50°W 18 Links (11.88')#1 24" Pine S35°E 34 Links (22.44')#2

Lyle S. Shepherd R.L.S. #503 Book 53, Pages 52 and 53 September 18, 1923 Planted Cedar stake, glass and leaf of old Buggy Spring

Robert A. Griffin R.L.S. #13584 LCRC #453 August 6, 1977 Found the Buggy Spring as called for in the 1923 notes by Lyle S. Shepherd. Replaced with a 5" sq. by 36" concrete monument with brass cap. 5" - 5" - 6" Triple Maple S53°E 67.98' #3

4" X 7' Post South 33.09' #4 34" Pipe S27°W 34.59' #5 3" Maple S62°W 43.44' #6 Concrete Monument West 13.20' #7

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found 5" square concrete monument with brass cap in the centerline of the dirt road going East and the centerline of the dirt road going North is 13 feet ± East. The condition of the recorded witnesses are: #1 and #2 gone, #3 uprooted, #4 gone, #5 thru #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted the 5" square concrete monument with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

74" Pipe S30°W 34.58' #5 12" Maple S65°W 43.78' Found spike in North side of tree. # Concrete Monument (Southwest Corner, Section 35, T14N F 8" - 6" Twin Maple S40°E 54.72' Set spike with tag #22439 ir 4" - 6" Clump Cherry N42°E 63.72' Set spike with tag #22439 in South	R13W) West 13.18' #7 1 Northeasterly side of tree.
Signed by Norman L. Ochs	DateDecember 18, 1998
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on	Revised May 14, 1975 Revised Jan., 1983

NORMAN L: OCHS 22439 PED LAND