

MAY 28 1857

1996 Newaygo County Remonumentation Project

'97 FEB 12 PM 4 45

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

NEW COUNTY

REGISTER OF DEEDS LINDA M. BROWN

	I ILING MEWOII	REMERT OF ACT 74, MICH. P.	A. 1970	. 1017	1. Deven
For corners in Newaygo (County)	Located in:	Corner Code #	Se Se	ndis III	· Wassing
1. Public Land Survey	T <u>13N</u> R <u>14W</u> T R T R	<u>C-1</u>	vol 1	PAGE	246
Property Controlling in Section Miscellaneous	TR STR STR STR				
Property in Sec.	\$TR	Regi	ister of Deeds_Stan	np & File_N	lumber
do hereby certify that under requ	in a field survey on <u>October 3</u>	A. of 1970, the corner	A B C D E	- 4 3	J K L M
therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poi conformance with the rules of	above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 an the Michigan Board of Land ished, re-established, monumer elow:	of the United States decree of a Court of d 5 above were in Surveyors or by a	7	-16	
Note: Not more than 4 or recorded on this or	corners, all in the same certificate.	town and range, may be	10 -30 - 29	-20	-2625- - -3538-
Northwest Corner, Section	n 5, Dayton Township, Ne	wavgo County, Michigan	13		
•		ND ACCESSORIES AND/OI	R SUBSEQUENT	RESTOR/	ATION:
G.L.O. Mullett and Brookfield 24" Beech S48°W 32 Links (10" Beech S73°E 16 Links (1 Southeast Corner, Section 3' Fast 22 Links (14 52'\#3	21.12')#1 (0.56')#2	Patrick A. Salisbury R.L.S. LCRC #341 May 1, 1975 Found Plow Point raised w Southeast Corner, Section 8" Catalog Sept 140,000	vith ½" Rod 131, Denver Townshi	ip, East 14.2	22' #3

Ralph A. Smith R.L.S. #3421 Book 55 Page 43 March 3, 1954 Fence Corner N35°W 29.3' #4 6" Pine N45°W 47.1' #5 12" Apple S20°W 64.5' #6 Iron, Stone, and Glass (Southeast Corner, Section 31, Denver Township) East 14.5' #3

Power Pole N61°E 104.86' #8 24" Pine N48°W 47.69' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR **REESTABLISHING CORNER:**

Found ½" X 18" Rerod, Plow Point, Crockery and a large stone in centerline of East and West gravel road and in the centerline of the gravel road going South and the centerline of the bituminous road going North is 15 feet East and the condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 gone, #5 good condition, #6 and #7 gone, #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" X 18" Rerod and Plow Point and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

	and tall the total state of the original control.
1/2" Rerod (Southwest Corner, Section 31, T14N R14W) East 14.2: 34" White Pine N45°W 47.1' Set spike with tag in East side of tree. Power Pole N64°E 104.94' Found spike in Northerly side of pole. # 18"-14"-12" Quadruplet Elm S22°E 72.59' Set spike with tag in 14" White Pine N09°W 82.90' Set spike with tag in Easterly side of	. #5 t8 t West side of tree.
Signed by Norman L. Ochs	DateOctober 17, 1996
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group On October 24, 1996	Revised May 14, 1975 Revised Jan., 1983

m. L.O.

NORMAN . Ochs LAND