

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

1996 Newaygo County Remonumentation Project

MAY 2.8 1997

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

ON MINIO			/	9				0						
For corners in Newaygo (County)	Located in:	Corner Code#			X	Lord	eida VN. 8				Orow			
1. Public Land Survey	T <u>13N</u> R <u>14W</u> T R T R	C-2	٧	0L.	1			PAG	ìΕ	2	, 4	7		
2. Property Controlling in Section	STR STR	•												
3. Miscellaneous Property in Sec.	STR STR		Register of	Dee	ds (Star	np 8	File	e N	lumi	<u>ær</u>		_	
4. Lot No, Reco	rded Plat	•	:	Λ <u>D</u>	C	U	E I	0	11	t	J f	C L		
5. Private Claims	ded Flat		2	— ÿ-	•	5					Į_		-	
			3		_[-	<u> </u>	_ _	_ _		_ _		1_	
I, Norman L. Ochs	in a field survey on October 7	. 19 96 .	4	_}.	_ _	ļ. 3.—	_	_[.	10.	_ _			[,	
do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner			5	_ _		ĺ			_Ï_	_ _			ĺ	
points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States			ß		_	17		.					Ĺ	
•						• •	. "			1 -	,,			

recovered, found as expressed below.

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,

West One Quarter Corner, Section 5, Dayton Towship, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John H. Mullett 1839 12" Beech S16°E 26 Links (17.16')#1 16" Beech S40°W 18 Links (11.88')#2

Newaygo Engineering and Survey Company June 1978

This corner was set on occupation - fence going West and on Section line between the Northeast Corner and the Southeast Corner of Section 6 (Note: Not ½ way on line) Set 1½" Pipe

8"-6"-4" Triple Maple S66°W 54.74' #3

24" Dead Elm (in East and West fence) West 54.12' #4

24" Maple S75°E 6.76' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1½" X 33" Iron Pipe on line ± with remnants of fence going West and the centerline of the North and South gravel road is 12'± West and the condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 dead, #5 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1½" X 33" Iron Pipe and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

10"-8"-4" Triple Maple S69°W 54.70' Found spike in North side of tree. #3
36" Maple S75°E 6.84' Found spike in North side of tree. #5
6" Maple N78°W 38.09' Set spike with tag in North side of tree.
4" Hickory N43°E 18 02' Spike with tag in West side of tree.

22439

Approved by Peer Review Group On October 24, 1996

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975 Revised Jan., 1983

Norman L. Ochs, County Representative.

Surveyor's Michigan License No.

