

MAR 02 1999

SECTION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 38

For corners in Newaygo (County)	Located in:	Corner Code #	Lind	e M. Brown
Public Land Survey	T <u>13N</u> R <u>14W</u> T R T R	C-13	VOL. $oldsymbol{2}$	e M. Brown 207
Property Controlling in Section Miscellaneous	STR STR STR			
Property in Sec.	S IR		Register of Deeds Stamp	& File Number
or nereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea _aw and/or that the corner poinconformance with the rules of	, in a field survey on May 13 rements of P. A. 74, Michigan P. above were in conformance with rotation of survey instructions of u of Land Management or by a nation of the Michigan Board of Land the Michigan Board of Land shed, re-established, monument	A. of 1970, the corner egulations and rules of the United States decree of a Court of I 5 above were in Surveyors or by a	2 6 - 5 - 4 - 3	-
Note: Not more than 4 c recorded on this ce	orners, all in the same to ertificate.	wn and range, may be	11	╸ ╂╌╂╌╏╌╂╌┤
Southwest Corner, Section 32	2, Dayton Township, Newaygo	County, Michigan,	12 - 31 + 32 + 33 + 33 + 33 + 33 + 33 + 33 +	34 + 35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 12" Beech S47°E 27 Links (17.82')#1. 12" Beech N57°W 54 Links (35.64')#2 Northeast Corner, Section 5, T12N R14W, East 43 Links (28.38')#3

Sammy S. Barnett R.L.S. #16923 LCRC #184 April 27, 1973 Found ½" Rod in centerline of M-82 in monument box Telephone Pole N28°W 54.30' #8 18" Maple S36°E 73.92' #9 Northwest Corner, Section 5, T12N R14W, East 28.43' #3 Newaygo County Road Commission Sheet Bolt In pavement "X" in concrete drive N40°E 59.0' #4 Telephone Pole N35°W 49.8' #5 Northeast Corner West Head wall S03°W 37.2' #6 Northwest Corner East Head wall S45°E 47.5' #7

John P. Clapp R.L.S. #14091
Recorded survey June 13, 1975
Found ½" Bar in monument box
Telephone Pole N28°W 54,30' #8
18" Maple S36°E 73.92' #9
Northwest Corner, Section 5, T12N R14W, East 28.43' #3

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found $\frac{1}{2}$ " X 17" Copper Rod in monument box on line \pm with bituminous road going North. The centerline of the East and West bituminous road is 1 foot \pm South. The condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 found old concrete drive broken up unable to locate "X", #5 thru #8 gone, #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Copper Rod and monument box and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northwest Corner, Section 5, T12N R14W (2¾" X 20" Harrison cast iron monument in monument box) East 28.50' #3 34" Maple S36°E 74.05' Set spike with tag #22439 in Northeasterly side of tree. #9 West end of Corrugated Metal Pipe S15°W 36.17' Set P.K. nail with tag #22439. 22" Walnut N26°E 77.60' Set spike with tag #22439 in West side of tree. Power Pole S58°E/94.17' Set spike with tag #22439 in North side of pole.

Signed by Norman L. Ochs	Date October 15, 1998
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on October 22, 1998	Revised May 14, 1975

11.8.0