MAR 0 2 1999

SECTION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 38

For corners in				•••
Newaygo (County)	Located in:	Corner Code#	Linda	m. Brown
1. Public Land Survey	T <u>13N</u> R <u>14W</u> T R T R T R	<u>E-7</u>	Linda VOL. 2	21(
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & Fil	e Number
do hereby certify that under requi points mentioned in lines 1 and 2 a therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poin conformance with the rules of	, in a field survey on <u>December 1</u> rements of P. A. 74, Michigan P.A. or above were in conformance with regular manual of survey instructions of the of Land Management or by a december of the Michigan Board of Land Surthe Michigan Board of Land Surthed. re-established. monumentad	f 1970, the corner ulations and rules ne United States cree of a Court of above were in	5 6 - 18 - 17 - 16 - 15 - 7	- 11 - 12 -
Note: Not more than 4 co recorded on this ce	orners, all in the same town rtificate.	and range, may be		- - -
Northeast Corner, Section 20,	Dayton Township, Newaygo Co	ounty, Michigan.	$\begin{array}{c} 12 \\ 13 \\ \end{array} + \begin{array}{c} 31 + 32 + 33 + 34 + \\ \end{array}$	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1838 24" Beech S51°E 50 Links (33')#1 10" Sugar N50°E 25 Links (16.5')#2

Lyle S. Shepherd R.L.S. #503 Witness Book Number 2, Page 7 ±1920's

12" Red Elm \$351/2°E 59' #3

Norman L. Ochs R.L.S. #22439 LCRC #625 September 14, 1984 Found 3/2" Iron 18" Maple N60°W 48,85' #4

Northeast Corner of store \$70°W 82.50' #5

Newaygo County Road Commission Sheet Iron 24" Elm S40°E 58,8' #3

15" Maple N60°W 49.2' #4

Paul Paquette R.L.S. #16938 August 1973 Recorded in Series F, Number 4905 Found Iron

No witnesses given.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING **CORNER:**

Found 3/2" X 24" Rod, driven into a 1" X 32" Iron Pipe. Also found small pieces of limestone 41/2 feet deep. On line ± with the centerline of the North and South bituminous road. The centerline of the East and West bituminous road is 1.5 feet ± South. The condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rod and Iron Pipe and set a 2¾" diameter Harrison cast iron monument 36" long marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northeast Corner Frame Building (measure taken to foundati	on) S68°W 82 48' #5
6" - 10" Twin Elm S24°E 83.62' Set spike with tag #22439 in I	Northeasterly side of tree
30" - 30" Twin Maple N11°W 116.08' Set spike with tag #224:	39 in East side of tree
	or in made diad of a do.
Signed by Morman L. Ochs	Date December 18, 1998
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Seath Surveyors, Jan 28, 1971

Approved by Peer Review Group on December 22, 1998 Norman L. Ochs, County Representative.

20" Maple N63°W 49.83' Set spike with tag #22439 in South side of tree. #4

May 14, 1975 Cysld Jan., 1983 NORMAN L. OCHS LAND SURVEYOR

OF MARRY

LAND