REGISTER OF DEED REGIST

MAR 02 1999

LAND CORNER RECORDATION CERTIFICATE 99 FEB 17 PM 3 40 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in SECTION Located in:	Corner Code #	Linds M.	Brown
(County) 1. Public Land Survey T 14N R 13W	<u>(c.)</u> /	vol. $oldsymbol{2}$	244
T 15N R 13W T R T R T R T R T R T R T R T R T R T R		egister of Deeds_Stamp & I	-ile Number
4. Lot No, Recorded Plat	June 16 , 19 98 , igan P.A. of 1970, the corner be with regulations and rules ctions of the United States	A B D E F G H 2 - 6 - 5 - 4 - 3 3 - 1 - 1 - 1 4 - 7 - 8 - 9 - 10 5 - 18 - 17 - 16 - 15	-
Law and/or that the corner points mentioned in lines 3 conformance with the rules of the Michigan Board of Decree of a Court of Law, established, re-established, morecovered, found as expressed below:	t, 4 and 5 above were in Land Surveyors or by a commented, re-monumented,	7 8 19 20 21 22 9 1 1 1 1 10 30 29 28 27	
Note: Not more than 4 corners, all in the sa recorded on this certificate.	ıme town and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1-1-1-1
Northeast Corner, Section 6, Lincoln Township, Net Southeast Corner, Section 31, Merrill Township, Ne	waygo County, Michigan. waygo County, Michigan.	13	
A. DESCRIPTION OF ORIGINAL MONUMEN	IT AND ACCESSORIES AND/C	OR SUBSEQUENT RESTO	PRATION:
G.L.O. Mullett and Brookfield 1838 12" Beech N65°E 37 Links (24.42')#1 8" Beech N03°W 59 Links (38.94')#2	William M. Jacques Book 44 Pages 16 a Found section corna	and 17 November 3, 1913	3
Delos G. Anderson (County Surveyor) Book A Pages 201 and 202 April 15, 1897 Old Corner	1857 G.L.O. Resur 14" Beech S12°E 23 12" Beech S63°W 4		on Nye
16" Pine Stump S40°W 22 Links (14.52')#5			OVER \$
B. DESCRIPTION OF CORNER EVIDENCE REESTABLISHING CORNER:	FOUND AND/OR METHOD AP	PLIED IN RESTORING O	₹ .
Found 5" X 5" concrete monument with brass of the Southwesterly and Northeasterly road is South. The condition of the recorded witnesse monument, #7 thru #10 good condition, #11 b	s 129 feet South. The extension es are: #1 thru #5 gone, #6 evide	of the centerline of road g	oing East is 48 feet
C. DESCRIPTION OF MONUMENT FOR CO THE POSITION OF THE CORNER:	ORNER AND ACCESSORIES E	STABLISHED TO PERPE	TUATE LOCATING
Accepted 5" X 5" concrete monument with bra careful and faithful reestablishment of the ong	ass cap as a substantial marker jinal corner.	for the section corner and	is accepted as a
28" Maple N37°E 54.32' Found dock spike in S Center of a Well (1½" Pipe) N50°E 91.38' to o Southwest Corner of a concrete slab S88°E 1 32"-32" Twin Red Oak S70°E 45.73' Found do 4" Square X 7' Treated Pine Post (broken off	enterline at base, #8 80.71' #9 ock spike in North side of tree. # at ground) N86°W 33' to face. #	11	
Signed by // Suman X. C/C	Date Nover	nber 3, 1998	
Surveyor's Michigan License No. 22439 Approved by Peer Review Group on November 10, 198		Michigan State Board of Land Sur	veyors, Jan 28, 1971 evised May 14, 1975 Revised Jan., 1983
Norman L. Ochs, County Representative.		Constitution of the state of th	
11. X. O.	[*/	NORMAN L. OCHS	

MARIO LAND

A. Description (cont.)

Road survey by Gerald Dyksterhouse R.L.S. #2734

1941 Monument not given

Corner is 268 feet West of the intersection of T.T. 153 (railroad grade) and East and West road. Corners West on the Point-of-Beginning of the road survey thru a point 40 feet North of the intersection of T.T. 153 and road centerline. #6

Robert A. Griffin R.L.S. #13584 LCRC #153 August 9, 1967

Searched for, but did not find evidence of a corner monument. By recovering the Point-of-Beginning of the Dyksterhouse road survey and extending a line from this Point-of-Beginning through a point 40 feet North of the intersection of T.T. 153 and road centerline 268 feet continued West of T.T. 153, I recovered the corner as called for in the 1941 notes of Gerald Dyksterhouse. This corner is 4 feet East of the centerline of a North and South road. I placed, at the exact location of the recovered section corner, a 5" square reinforced concrete post, with brass disk, 3 feet in length, set one foot below the surface.

18" Maple N33°E 54.32' #7

Center of a Well (1½" Pipe) N48°E 91.35' #8

Southwest Corner of a concrete \$\tilde{1}\text{ab}\text{ (13' East and 17' North) N88°E 180.85' #9

15"-19" Twin Red Oak S71°E 45.80' #10

4" Square by 7' Treated Pine Post West 33' #11

SUFFYEY & REMONDINGUES ON

MAR 0 2 1999

SECTION