MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYOU COULTY REGISTER OF DEEDS LINDA M. BROWN.

SECTION

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 37

For corners in Newaygo (County)	Located in:	Corner Code #	Linda	m. Oi
Property Controlling in Section Miscellaneous Property in Sec.	T 14N R 11W T 14N R 12W T R T R S T R S T R S T R S T R	A-3 M-3	VOL. 2 Register of Deeds Stamp & File	Number
do hereby certify that under re points mentioned in lines 1 and therefore as required in the co Department of the Interior, Bu	, in a field survey on October equirements of P. A. 74, Michigan P. d 2 above were in conformance with urrent manual of survey instructions reau of Land Management or by a	A. of 1970, the corner regulations and rules of the United States decree of a Court of	A B C D E F G H I 2 - 6 - 5 - 4 - 3 - 3 - 3 - 4 - 7 - 8 - 9 - 10 - 5 - 6 - 18 - 17 - 16 - 15 - 7	+ + + -
conformance with the rules Decree of a Court of Law, est recovered, found as expressed	corners, all in the same to	Surveyors or by a sted, re-monumented,	8 - 19 - 20 - 21 - 22 - 9 10 - 30 - 29 - 28 - 27 - 11 12 - 31 - 32 - 33 - 34 - 1	26 - 25 -
	n 6, Goodwell Township, Neway 1, Wilcox Township, Newaygo		13	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1838 6" Beech N52°E 22 Links (14.52')#1 5" Beech S61°E 32 Links (21.12')#2

Lyle S. Shepherd R.L.S. #503
Book 36 Pages 90 and 91 September 16, 1916
Witness Book Number 1 Page 5
Found old stake. Set new stake.
30" Pine Stump N18½°E 56.5' #3
5" Black Oak S34¾°E 17.0' #4

Ralph A. Smith R.L.S. #3421 Witness Book Number 1 Page 5 ½" Iron Northeast leg of Tower S21°E 94.0' #5 16" Maple S57°W 69.5' #6 24" White Oak N38°W 109.0' #7

LAND

OVER ♥

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" Grounding Rod 4 feet deep. The centerline of the North and South power line access drive is 66 feet East. There is a cedar post for fence running South and West 0.5 feet. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #10 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northeast Leg Tower #4200 S15°E 93.9' #5 32" Red Oak S60°W 69.78' Set spike and tag in Southeast sig 36" Red Oak N25°W 109.75' Set spike and tag in Northeast sig 22" Red Oak East 87.95' Found old spike and set new spike a	ide of tree. #7			
8" Cedar Post Southwest 1.0' #9				
16" Poplar N35°W,76.7' Set new spike and tag over old spike	in South side of tree, #10			
Signed by Norman L. Ochs	_ DateOctober 7, 1997			
Norman L. Ochs				
Surveyor's Michigan License No. 22439	Form approved by Michigan State Roard of Land Surveyors, Jan 28, 1971 Revised May 14, 1975			
Approved by Peer Review Group on October 14, 1997	Revised May 14, 1975 Revised Jan., 1983			
Norman L. Ochs, County Representative.	NORMAN			
M.L.O.	L OCHS			

A. Description (cont.)

Ronald J. Ruszala R.L.S. #21581 LCRC #370 November 25, 1975 Found ½" Rebar next to the Corner Fence Post, located 33 feet West of the centerline of Tower line. 22" Oak S55°W 69.78' #6 20" Oak N32°W 109.56' #7 Top Bolt on North side of Northeast leg of Tower S21°E 93.65' #5

Newaygo Engineering and Survey Company
April 9, 1984 Field notes
Found ½" Rebar
22" Oak S55°W 63.67' #6
20" Oak N32°W 109.33' #7
Top Bolt North side on Northeast leg of Tower S21°E 93.65' #5

Allan L. Meyer R.L.S. #15406 LCRC #999 February 1990 Found ½" Rebar 22" Oak S55°W 69.78' #6 20" Oak.N32°W 109.56' #7 Top Bolt on North side of Northeast Tower leg S20°E 93.65' #5 16" Oak East 88.05' #8 Cedar Post Southwest 1.0' #9 10" Poplar N50°W 77.0' #10