NEWAYGO COUNTY REGISTER OF DEEDS

MAR 1 3 2000

1999 Newaygo County Remonumentation Project LINDA H. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICAT® FEB 28 PM 1 17. FILING REQUIREMENT of Act 74, Mich. P.A. 1970

	FILING ILEGOINEM	LIVI OI ACCIA, INICII.	A A	
For corners in  Newaygo (County)	Located in:	Corner Code #	Linda M. Br	swel
1. Public Land Survey	T <u>14N</u> R <u>12W</u> T <u>14N</u> R <u>11W</u> T R T R	M-9 / A-9	, vol. $oldsymbol{2}$	353
Property Controlling     in Section	sTR sTR		TUL. A	999
3. Miscellaneous	STR			
Property in Sec.	SR		Register of Deeds Stamp & File	
4. Lot No, Record 5. Private Claims	ed Plat		A B C D E F G H I 2 F 6 + 5 + 4 + 3 +	J K L M
do hereby certify that under requirements mentioned in lines 1 and 2 at therefore as required in the current Department of the Interior, Bureau Law and/or that the corner point conformance with the rules of the state of the st	, in a field survey on	f 1970, the corner lations and rules e United States ree of a Court of above were in veyors or by a	3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 21	14 - 13 -
•			10 30 + 29 + 28 + 27 +	26 - 25 -
recorded on this ce	orners, all in the same town rtificate.	i and range, may be	11	
Southeast Corner, Section 24, Wilcox Township, Newaygo County, Michigan. Southwest Corner, Section 19, Goodwell Township, Newaygo County, Michigan.			12 31 + 32 + 33 + 34 + 13	35 + 36 -
A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:				
G.L.O. John Hodgson 183 8" Beech S25°W 25 Links (16" Maple N76°W 16 Links Norman L. Ochs, R.L.S. #2 May 31, 1983 Found ½" If glass. Raised with a 1" Pip Northwest Leg Tower S45°	(16.5')#1 (10.56')#2 (2439 ron, old wood stake and le	22" Pine Stump N75  Lyle S. Shepherd R Book 36, Page 90	and 222 1898 ± J°E 59 Links (38.94')#3 5°E 23 Links (15.18')#4	oe
Northeast Corner House \$45°W 92.65' #7 24		24" Pine Stump S14		
16" - 14" Twin Birch N35°E	17.63' #8	8" Black Oak N64%	€ 61' #5	OVER 🤟
B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:				
Found 1" x 2' Pipe above a ½" Rod and 2.5 feet below grade found broken glass and crockery. Corner is in the centerline of the East and West gravel road and is 1 foot West of the centerline of the North and South gravel road. The condition of the recorded witnesses are: #1 thru #5 gone, #6 and #7 good condition, #8 gone, #9 thru #11 good condition.				
C. DESCRIPTION OF MO THE POSITION OF THE C	NUMENT FOR CORNER AN	ND ACCESSORIES E	STABLISHED TO PERPETU	ATE LOCATING
Removed Pipe and Rod and marker for the section com	set a 4" diameter Harrison cas er and is accepted as a care	stiron monument 18" lo ful and faithful reestak	ong marked "County Surveyor" olishment of the original corner	' as a substantial
Northwest Leg of Tower S5 Northeast Corner of House Northeast Leg of Tower N6 30" White Oak S67°W 78.0 Power Pole N61°W 58.81" Signed by	\$50°W 92.64' #7	389 in Southwest side	#10 of pole. #11 gust 16, 1999	
Norman L. Ochs Surveyor's Michigan License N	la. <u>22439</u>	Form approved by I	Michigan State Board of Land Surveyor	s Jan 28 1971
Approved by Peer Review Group of Norman L. Ochs, County Represent	n October 28, 1999		Revise	d May 14, 1975 ised Jan., 1983

L OCHS

A. Description (cont.)

William Fries, Jr. R.L.S. #30389
LCRC #910 April 20, 1989 Found 1½" outside diameter Pipe in the centerline of the North-South and East-West roads.
Northeast Tower Leg S56°E 64.28' #9
Northeast Corner House #1595 S52°W 92.61' #7
24" Oak (nail in root) S69°W 78.84' #10
Power Pole N58°W 58.82' #11

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION