

MAR 1 3 2000

1999 Newaygo County Remonumentation Project REGISTER OF DEEDS

**NEWAYGO COUNTY** LIMBA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970' 00 FEB 28 PM 1 17

SEC	TION

For corners in Newaygo (County)	Located in:	Corner Code #	Linds YN	. Brown
Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R <u>14W</u> T <u>15N</u> R <u>14W</u> T <u>15N</u> R <u>13W</u>	A-1 M-1 / M-13 A-13	$^{\circ}$ VOL. ${f 2}$	354
Property Controlling     in Section	STR STR			
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & F	ile Number
do hereby certify that under re points mentioned in lines 1 and therefore as required in the Coppartment of the Interior, But Law and/or that the corner conformance with the rules	, in a field survey on October 9 quirements of P. A. 74, Michigan P.A. I 2 above were in conformance with regirent manual of survey instructions of reau of Land Management or by a depoints mentioned in lines 3, 4 and 5 of the Michigan Board of Land Stablished, re-established, monumented	of 1970, the corner pulations and rules the United States becree of a Court of 5 above were in urvevors or by a	B C D E F G H  2 - 6 - 5 - 4 - 3  3 - 1 - 1 - 16 - 15  7 - 8 - 19 - 20 - 21 - 22	14 - 13 -
Note: Not more than 4 recorded on this	corners, all in the same tow certificate.	n and range, may be		
Northeast Corner, Section Southeast Corner, Section	6, Lincoln Township, Newaygo Co 1, Denver Township, Newaygo Co 36, Beaver Township, Newaygo C 31, Merrill Township, Newaygo C	ounty, Michigan. County, Michigan.	11 12 - 31 - 32 - 33 - 34 1	35 + 36 -

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1838 9" Cedar (no bearing given) 16 Links (10.56')#1 16" Hemlock N40°E 35 Links (23.1')#2

William M. Jacques (County Surveyor) Book 44 Page 17 November 3, 1913 Found old stake.

Norman C. Caldwell R.L.S. #12018 LCRC #1124 July 1991 Placed 36" x 30" with brass cap aluminum monument. Centerline of old two track road 3 feet below surface. 8" Maple S48°W 47.45' #3 6" Maple N56°E 39.30' #4 6" Maple S87°E 9.80' #5 Carsonite Witness Post West 7.7' #6

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found brass cap on top of rod in the centerline of the North and South trail road. Woven fence on ground going West is 33 feet North. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted brass cap on top of rod as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

16" Maple S50°W 47.59' Found spike in Northwest side of tree. #3 10" Maple N60°E 39.37' Found spike in Southeast side of tree. #4 8" Maple S86°E 9.86' Found dock spike in South side of tree. #5 Carsonite Witness Post N85°W 7.69' #6 6" diameter by 41/3' Steel Post N30° JV 40.55' Mman Signed by October 22, 1999 Norman L. Ochs Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Approved by Peer Review Group on December 16, 1999 Norman L. Ochs, County Representative.

MICHIE D F NORMAN L. OCHS AND 22439 TO LAND

Revised Jan., 1983