



CONTINUATION OF "A" - DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

Robert A. Griffin, R.L.S. #13584 - L.C.R.C. #123

Found 1" iron pipe in West edge of a graded earth road replaced with 5" square reinforced concrete post with brass disk.

18" B. Oak N43°E 66.21' (O.B.T.) #5

6" W. Oak S58°E 98.86' #6

9" B. Oak S23°W 53.08' #7

4" Sq. x 7' Pine Post West 33' #8

7" R. Pine N38°W 165.21' #9

Robert L. Wetherell, R.L.S. 24624 - September 18, 1989

Recorded in Liber 349, Page 2366

22" B. Oak N43°E 66.21' #5

9" W. Oak S58°E 98.86' #6

11" B. Oak S28°W 53.08' #7

12" R. Pine N38°W 165.21' #9

Measured 2596.18 feet from the East 1/4 corner to the Center 1/4 corner Section 7. Measured 2635.13 feet from West 1/4 corner to Southwest corner Section 8.