

MAR 0 2 1999

NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

Surveyor's Michigan License No.

Approved by Peer Review Group on November 10, 1998
Norman L. Ochs, County Representative.

22439

LAND CORNER RECORDATION CERTIFICATE 99 FEB 17 PM 3 49 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

| For corners in Newaygo  | Located in:  | Corner Code #   | Linda M. Brown  |             |  |
|---|--|---|---|-------------|--|
| (County)  |  |   |   |             |  |
| 1. Public Land Survey   | T <u>14N</u> R <u>13W</u><br>T <u>15N</u> R <u>13W</u><br>T R  | C-13 C-13   | VOL. $oldsymbol{2}$   | 244         |  |
| Property Controlling     in Section     Miscellaneous   | TR<br>STR<br>STR<br>STR  |   |   |             |  |
| Property in Sec.  | STR  | R   | Register of Deeds Stamp & File Number   |             |  |
| 5. Private Claims   |  |   | 1 A B D E F G H 2 - 6 + 5 + 4 + 3 3   | J K L M     |  |
| do hereby certify that under requestioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner poconformance with the rules of Decree of a Court of Law; estab recovered, found as expressed to   |  | or 1970, the corner egulations and rules fithe United States decree of a Court of 5 above were in Surveyors or by a d, re-monumented, | 5   1   1   1   1   1   1   1   1   1   | - 23 - 24 - |  |
| Note: Not more than 4 or recorded on this o   | corners, all in the same to<br>ertificate.   | wn and range, may be  | $ \begin{array}{c ccccccccccccccccccccccccccccccccccc$  | 35 + 36 -   |  |
| Northeast Corner, Section 6, Lincoln Township, Newaygo County, Michigan.  Southeast Corner, Section 31, Merrill Township, Newaygo County, Michigan.   |  |   |   |             |  |
| A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:  |  |   |   |             |  |
| G.L.O. Mullett and Brookfield 1838<br>12" Beech N65°E 37 Links (24.42')#1<br>8" Beech N03°W 59 Links (38.94')#2   |  | Book 44 Pages 16 a  | William M. Jacques (County Surveyor)  Book 44 Pages 16 and 17 November 3, 1913  Found section corner. |             |  |
| Delos G. Anderson (Cour<br>Book A Pages 201 and 2<br>Old Corner   | 02 April 15, 1897  | 1857 G.L.O. Resul<br>14" Beech S12°E 2<br>12" Beech S63°W 4   |   | on Nye      |  |
| 16" Pine Stump S40°W 2  | 2 LINKS (14.52)#5  |   |   | OVER \$     |  |
| B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  |  |   |   |             |  |
| Found 5" X 5" concrete monument with brass cap. The centerline of gravel road going North is 4 feet West. The centerline of the Southwesterly and Northeasterly road is 129 feet South. The extension of the centerline of road going East is 48 feet South. The condition of the recorded witnesses are: #1 thru #5 gone, #6 evidence of railroad grade 270 feet East of monument, #7 thru #10 good condition, #11 broken off at ground. |  |   |   |             |  |
| C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  |  |   |   |             |  |
| Accepted 5" X 5" concrete monument with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.  |  |   |   |             |  |
| Center of a Well (11/4" Pip<br>Southwest Corner of a co   | Found dock spike in Southe<br>be) N50°E 91.38' to centerlir<br>oncrete slab S88°E 180.71' a<br>70°E 45.73' Found dock spik | ne at base. #8<br>#9  | 40  |             |  |
|   | ine Post (broken off at grout  |   |   |             |  |
| Signed by Norman L. Oc  | n a. Chero   | DateNove  | mber 3, 1998  |             |  |

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975

Revised Jan., 1983 OF MICHIGA NORMAN L. OCHS

## A. Description (cont.)

Road survey by Gerald Dyksterhouse R.L.S. #2734

1941 Monument not given

Corner is 268 feet West of the intersection of T.T. 153 (railroad grade) and East and West road. Corners West on the Point-of-Beginning of the road survey thru a point 40 feet North of the intersection of T.T. 153 and road centerline, #6

Robert A. Griffin R.L.S. #13584 LCRC #153 August 9, 1967

Searched for, but did not find evidence of a corner monument. By recovering the Point-of-Beginning of the Dyksterhouse road survey and extending a line from this Point-of-Beginning through a point 40 feet North of the intersection of T.T. 153 and road centerline 268 feet continued West of T.T. 153, I recovered the corner as called for in the 1941 notes of Gerald Dyksterhouse. This corner is 4 feet East of the centerline of a North and South road. I placed, at the exact location of the recovered section corner, a 5" square reinforced concrete post, with brass disk, 3 feet in length, set one foot below the surface.

18" Maple N33°E 54.32' #7

Center of a Well (1½" Pipe) N48°E 91.35' #8

Southwest Corner of a concrete sfab (13' East and 17' North) N88°E 180.85' #9

15"-19" Twin Red Oak S71°E 45.80' #10

4" Square by 7' Treated Pine Post West 33' #11



MAR 0 8 1999

SECTION