# SURVEY & REMONUMENTATION

MAR 1 9 1998

#### 1997 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. DROWN

'98 MAR 6 PT 12 37

SECTION For corners in				
Newaygo (County)	Located in:	Corner Code#	خ ا	Linea m. Brun
1. Public Land Survey	T <u>15N</u> R <u>14W</u> T R T R T R		YOL. $oldsymbol{2}$	123
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR		Register of Deeds Stamp	& File Number
I, Norman L. Ochs do hereby certify that under rec points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bur Law and/or that the corner p	, in a field survey onOctober 1 juirements of P. A. 74, Michigan P.A. 2 above were in conformance with re rent manual of survey instructions of eau of Land Management or by a coints mentioned in lines 3, 4 and	of 1970, the corner agulations and rules fithe United States decree of a Court of 5 above were in	A B C D E F G  1	3 - 2 - 1 - 10 - 11 - 12 -
	f the Michigan Board of Land S olished, re-established, monumente below:		8 - 19 - 20 - 21 -	<del></del>
Note: Not more than 4 recorded on this	corners, all in the same tov certificate.	wn and range, may be	10 - 30 + 29 + 28 + 11 + 12 + 31 + 32 + 33 +	+
South One Quarter Corner,	Section 2, Beaver Township, No	ewaygo County, Michigan.	13 32 33	

#### A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1857 48" Hemlock N35°W 16 Links (10.56')#1 10" Beech S16°E 12 Links (7.92')#2

Deios G. Anderson (County Surveyor) Book A Pages 251 and 252 May 10 and 11, 1899 Original Corner Newaygo County Road Commission Sheet 3/4" Iron
Power Pole N66°W 78.4' #3
10" Maple S10°W 87.8' #4
20" Maple S51°E 132.7' #5

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" X 21" Solid Shaft (top is 1" diameter threaded with nut) above ¾" Rod on line with old fence going South. The centerline of the East and West bituminous road is 1.5 feet South. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #5 good condition.

### C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ¾" X 21" Solid Shaft and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" over ¾" Rod as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole N63°W 78.60' Found spike in South side of pole.	#3
24" Maple (blazed) S11°W 87.80' Set spike and tag in West s	ide of tree. #4
36" Maple S50°E 132.70' Set spike and tag in Southwest side	
4" Birch N80°E 1/39.33' Set spike and tag in South side of tree	
$\mathcal{M}$ $\mathcal{O}$ $\mathcal{O}$	
Signed by Abman & Ochs  Norman L. Ochs	DateNovember 10, 1997
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
···	Revised May 14, 1975
Approved by Peer Review Group on November 11, 1997	Revised Jan., 1983
Norman L. Ochs, County Representative.	

