LIBER 21028 - 533

LIBER 21028 PAGE #9.00 MISC RECORDING
#9.00 MISC RECORDING
#2.00 REMONUMENTATION
01/27/2000 08:21:22 A.M. RECEIPT# 6
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER D

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			
Oakland	Located in:	Corner Code #	
(County)			
1. Public Land Survey	T <u>2N</u> R TR TR TR		Compliance with ACT 345, P.A. 1990
Property Controlling     in Section     Miscellaneous	S TR S TR S TR	REMONUMENTATION	ACT 345, P.A. 1990 APPROVED ON: 7-21-99 JL OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Property in Sec.	S TR	<u>MAR 21</u> 2000	Register of Deeds Stamp & File Numb
		SECTION	
4. Lot No, Reco	rded Plat		ABCDEFGHIJK
5. Flivate Clathis			2 - 5 - 4 - 3 - 2
Grant I Ward RIS	in a field survey on	December 10 1998 do hereby state that t	3 3 4 4 7 8 9 10 11
I, Grant J. Ward, R.I.S., in a field survey on <u>December 10 19 98</u> do hereby state that un requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and			were in 5   12   15   14   17   16   15   14   17   16   15   14   17   16   17   17
that the corner points mentioned	d in lines 3, 4 and 5 above y a Decree of a Court	e were in conformance with the rules of the Micl of Law; established, re-established, monume	nicnigan

- A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

Post, per G.L.O. Notes. F-3

on this certificate.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - North 1/4 Corner of Section 9, T. 2 N., R. 7 E. Found 1/2" Iron Rod in existing Monument Box in the F-3 Centerline of Commerce Road.

Previously Recorded in L. 6405 P. 386 (2), L. 12432 P. 335 (3), L. 12652 P. 104 (3) and L. 14836 P. 465 (3) of Oakland County Records.

(n) Indicates the number of references that confirms this corner by dimensional tie.

This corner location is accepted by the contractor and is generally accepted by professional surveyors

as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

of Sica.	F-3 Set	5/8" Rod and Remonumentation Cap in existing Monument Box.
The same of the sa	N 20° E	30.40' Set 60d Nail & Remonumentation Disc in East face of
2 5	.,	Utility Pole.
GRANT J. %	N 65° E	42.00' Set 60d Nail & Remonumentation Disc in Southeast
WARD .		face of 38" Oak.
LAND X	S 05° W	30,37' Set 60d Nail & Remonumentation Disc in Southwest
SURVEYOR	3 03 11	face of 36" Oak.
NO.	N 50° W	56.90' Set 60d Nail & Remonumentation Disc in Northeast
22445	M OC M	face of 10" Cherry
	O a contra	59.85' Found Monument.
LAND SU	South	
	Ille	Date July 12 1999
Signed by		July 12, 1738
Surveyor's Michigan License 160. 2	2445	

JULY 3, 1999

Corner Code: F-3

DOSSIER FOR: THE SOUTH 1/4 CORNER OF SECTION 4, MILFORD TOWNSHIP, T 2 N, R 7 E, OAKLAND COUNTY, MICHIGAN. Prepared under contract with the County of Oakland Under Act 345 of the Public Acts of 1990.

## **HISTORY:**

This Corner has been accepted and used since before 1974, as evidenced by recordings under Act 74 of the Public Acts of 1970 by Gary R. Stonerock, Surveyor as recorded in Liber 6405, Page 386.

## **COLLATERAL EVIDENCE:**

We found a 1/2" iron rod in an existing monument box and set a 5/8" iron rod and remonumentation cap in its place. This Corner lies in the Centerline of Commerce Road 33 feet North of and on line with fence corner. There is a concrete monument 59.85 feet South of the Corner. We measured 1.11 feet and 0.02 feet more than the recorded distances to the Northwest and Northeast Corners of Section 9, respectively.

We searched at least 50 feet in each direction for other stakes and found none that

might represent the Corner.

## SURVEYOR'S RECOMMENDATIONS:

This corner location is accepted by the Contractor and is generally accepted by Professional Surveyors as the best available evidence of the position of the original Corner. Therefore, I recommend that the Peer Review Group accept this Corner as monumented, with the references as shown on the enclosed form prepared according to Act 74 of the Public Acts of 1970.

Grant J. Ward, R.L.S. License No. 22445

SURVEY & REMONUMENTATION

MAR 21 2000

SECTION