## SLIEVEY & REMONUMENTATION

MAY - 1 1995

## UBER 15288 PG 533

## Mar 1095040447

OK - T. SMITH

COM	MIS	3SIC	NC
-----	-----	------	----

LAND CORNER RECORDATION CERTIFICATE 7.00 HISC RECORDING CHG - IN HOUSE 2.00 REMON CHG - IN HOUSE

10

11

12

Fo	r corners in Oak	land	Commerce Twp.			PAID RECORDED - OAKLAND COUNTY			
	(County)	<del></del>	Located	In:	Corner Code ##	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS			
Public Land Survey		ý	2N 8E T R T R T R		H-1	Compliance with ACT 345, P.A. 1990 APPROVED ON: 12-27-94 OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE			
2.	Property Controllin	-	T T	_ R		TON ON COMMITTEE			
3.	Miscellaneous Property in Sec.	<b>S</b> _	S T R R R Register of Deeds Stamp & File Number						
						A D O D E T O M I O K E			

December 21 David Pawlaczyk in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

No corner was set referencing original government land office notes. No L.C.R.C. was ever recorded for H-1, T-2-N., R-8-E., No. L.C.R.C. was ever recorded for H-13, T-3-N., R-8-E. No falling was ever recorded on G.L.O. notes for H-13, H-1.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 3/4" iron rod in an existing monument box in asphalt pavement currently occupies this corner. This corner is on  $\pm$  centerline Bogie Lake Road extended north and  $\pm$  260' west of the centerline Oxbow Road to the north. A bent "T" iron was found 33.0' S. and 33.5' E. at the base of old wood fence post.

Field measurements were made between the following 6 corners:

17632

Surveyor's Michigan License No.

H-1 to 1-1 2619.92 meas. 2547.41 H-1 to G-1 meas. H-1 to H-2 2654.90 meas. Oakland County Planning 2654.43 rec. Property desc.

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I replaced the 3/4" pipe in an existing monument box with a 5/8" x 24" iron rod with a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #17632".

P.K. nail and O.C.R. tag in N.W. face D.E. pole N.40° E. 65.47 S.21° E. P.K. Nail and O.C.R. tag N. face 6" Maple 68.20' S.18° W. P.K. nail and O.C.R. tag N.W. face D.E. pole 106.98'

N.38° W. 29.80' P.K. nail and O.C.R. tag N.E. face 20" Maple

The selected location is accepted by me and generally accepted by Professional Surveyors as the best are evidence of the position of the griginal corner.

2-16-95 Date .. Signed by

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

1.00

MICH/6

DAVID

PAWLACZYK

LAND SURVEYOR NO.

7632