MAY - 1 1995

LIBER 15288 pc 505

LAND CORNER RECORDATION CERTIFIED Requirement of Act 74, Mich. I Commerce Twp.		OK - T. SMITH RTIFICATE 7.00 MISC RECORDING CHG - IN HOUSE P.A. 1970 MAR 93 4:01 P.M. RECEIPT# 177B PAID RECORDED - OAKLAND COUNTY			
ted In: Corner Code ##		LYNN D. ALLEN, CLERK/REGISTER OF DEEDS			
N R 8E R R R R R R R R R R R R R R R R R	M-10	Compliance with ACT 345, P.A. 1990 APPROVED ON: 12-13-94 OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE			
		Register of Deeds Stamp & File Number			
		A B C D E F G H I J K L M			

Filing Requirement of Act 74, Mich. P.A. For corners in Commerce Twp. Oakland Located In: Corner Code ## (County) T 2N ... R 8E **Public Land Survey** <u>M-10</u> T _____ R ____ T ____ R ____ Property Controlling S ____ T ___ R _ in Section S ____ T ____ R ____ S ____ T ___ R ____ Miscellaneous Property in Sec. _ , Recorded Plat __ 5. Private Claims ___ David Pawlaczyk in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration:

	Post	G.L.O.	A. Holmes	N/A	Notes
1986	1" Rod in a monument box	L.C.R.C.	D. Griggs	#23511	L9773 P734
1989	Iron pipe in mon. box	L.C.R.C.	G. Stephens	#29252	L11381 P060

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1" pipe in a monument box in asphalt pavement currently occupies this corner. The following ties were used to verify and recover the present location of this corner.

2 ties from L.C.R.C.

L11381 P060

asurements w	rere made b	etween the follo	wing corners:
2642.26	meas.	•	
2640.00	rec.	G.L.O.	Notes
2642.33	rec.	Survey	L8678 P455
2642.00	rec.	Survey	M. Baldwin (1927)
2665.04	meas.		
2640.00	rec.	G.L.O.	Notes
2665.00	rec.	L.C.R.C.	L10966 P422
	2642.26 2640.00 2642.33 2642.00 2665.04 2640.00	2642.26 meas. 2640.00 rec. 2642.33 rec. 2642.00 rec. 2665.04 meas. 2640.00 rec.	2640.00 rec. G.L.O. 2642.33 rec. Survey 2642.00 rec. Survey 2665.04 meas. 2640.00 rec. G.L.O.

of MICHIO

DAVID **PAWLACZYK LAND** SURVEYOR NO.

17632

LAND

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1" pipe with a 5/8" by 24" iron rod with a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #17632" in an existing monument box.

	71.29' 171.75' 96.99'	P.K. nail and O.C.R. tag in N.W. face D.E. pole Centerline east bolt of traffic signal P.K. nail and O.C.R. tag in S.W. face traffic pole	
1.54° W.	70.75	P.K. nail and O.C.R. tag in N.E. face D.E. pole	
Tue south	385.11'	Found 1" iron rod in monument box	

The selected location is accepted by me and generally accepted by Professional Surveyors as the best a evidence of the position of the original corner.

Signed by Surveyor's Michigan License No. ___17632