SURVEY & REMONUMENTATION

UBER 17055 PG 773

MAR 0 4 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION	
Oakland Located In: Troy Twp. Corner Code #	
(County)	
1. Public Land Survey T_2N R_11E H-9	
<u>TR</u>	
TR	
2. Property Controlling S TR	2.26.97 13
in Section S TR	Ald.'
3. Miscellaneous S TR	1500
Property in Sec. S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKLM
5. Private Claims	
	2 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
. Wester K Kennedy	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, Huston K. Kennedy, in a field survey on 1/7, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan)
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented	
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 33 34 35 36
2.) 1990-Donnelly, PS #25829; LCRC L.11545, Pg.148 - Fnd capped 1" Iron Rod #25829 3.) 1993-Van Havermaat, PS #33988; LCRC L.13517, Pg.566 - Set 1/2" x 36" Rerod in 4	" diameter concrete Recurring to a RECEIPTH 105A RECURRING TO THE TOTAL AND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
B. Description of corner evidence found and/or method applied in restoring or reestablishing of the 1997 Kennedy Surveying, Inc Kennedy, PS #17623 - Fnd broken Concrete Monument in East & West, which has a concrete surface. A fence-tree line extending to the is 19 feet to the South and 44 feet North of the back curb for the West bound #25829 3.26 feet to the North.	the median of Big Beaver Road extending to the North. The back of curb for the East bound lane
Witnesses from LCRC #3 were used to recover and verify the location of the four	nd broken Concrete Monument.
I accepted the found broken Concrete Monument as the best evidence of the orig	inal corner position.
Field measurements between see back side of LCRC	ŕ
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
H-9 I replaced the found broken Concrete Honument with a 4" diameter Concrete Honum stamped Oakland County Remonumentation, PS #17623 SO2°E 104.88' NW corner of building #1 of Charter Square S20°W 60.80' Center of Bolt on top nut of Fire Hydrant N08°W 140.34' Set PK & Remon Washer East face 26" Haple N21°E 133.43' Set PK & Remon Washer NW face 23" Pine North 3.26 Ft. Fnd 1/2" capped Iron Rod #25829	HUSTON
North 3.26 Ft. Fnd 1/2" capped Iron Rod #25829 The selected location is accepted by me and is generally accepted by Professional : position of the original corner.	Surveyors as the best and able by the or the
Signed by Date Date	Z-Z7-9- POFESSIONAL
Surveyor's Michigan License No. 17623	willillillillillillillillillillillillill

SURVEY & REMONUMENTATION

MAR 0 4 1998

SECTION

FIELD MEASUREMENTS BETWEEN

H-9 to G-9

GLO = 40.49 chains or 2672.34 Ft.
"REPLAT OF OUTLOT "A" OF BIG BEAVER" + "BIG BEAVER" + "EYSTER'S BEAVER GARDENS" = 2722.60 Ft.
"FROST SUNNY ACRES" + Parcels = 2722.48 Ft.
GPS-MEA = 2722.74 Ft.

H-9 to I-9

GLO = 40.49 chains or 2672.34 Ft.
"SUPERVISOR'S PLAT NO. 9" = 2652.07 Ft.
"SUPERVISOR'S PLAT NO. 9" + "FORD SUBDIVISION" + Parcels = 2651.03 Ft.
GPS-MEA = 2650.86 Ft.