MAY 24 2000

LIBER 21119 - 611

SECTION

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

51692

F	or corners in			}	- 1	9.0	O H	CMINI	ECOR	DING	611 1	90	reto	TA 1.				
_	Oakland Located In: Corner Code # (county) Waterford Township					02/18/2000 02:36:27 P.M. RECEIPI# 1/ PAID RECORDED - OAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER D												
1. Public Land Survey T <u>3N</u> R <u>9E H-5</u> T_ R T_ R						Compliance with ACT 345, P.A. 1990												
	Property Controlling S T R CARCOLLING S							PROVED ON: 12-14-95 JU KLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE gister of Deeds Stamp & File Number										
4.	Lot No, Record	ed Plat	•															
	Delivate Oleina					<u> </u>	9	C P	E	F	G	'	\dashv	*				
					2	ģ	'	š . 	†	- à	- 3	'+	-2-	士				
of	Joseph C. Kapelczek, in a field sur P.A. 74, Michigan P.A. of 1970,	the corner points	mentioned in lines 1 ar	nd 2 above were in	4		,					\Box	{11-	I				
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a									+	 	Н	-	+	+				
decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in								17-	+	-1 <mark>B</mark>	1	•	14-	+				
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed								+	+	+		十	+	十				
be	elow:		•		8	1) 	9	<u>—20</u> 		-21	2	2	23	I				
	Description of activity to the second				10	3		2B	I	28-		$ \bot $	_26	I				
A.	Description of original monun	nent and accesso	ories and/or subsequer	nt restoration:	11	_ <u> </u>		1	_	Î.	آبا	-	+	+				
	Set post in 1816 G.L.O. Surve	ey.	•		12	3	1	<u></u> 32	+	33	-3	•	-35-	+				
	There are two LCRC's record	ded at Oakland C	County; Wozniak 1995 a	and Jones 1974.	13 L		1			1	Ll	i						
₿.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:																	
	Recovered an iron in monument box at centerline of Hatchery Road 4" \pm beneath the asphalt at this location. This corner was validated with monumentation recovered in Riverview Meadows No. 1 and Riverview Subdivision being the southwest corner of the southwest 1/4 of Section 10.																	
	Recovered Witnesses:																	
	South 19.55' PK nall atop gua S 45°E 26.13' PK nail atop gu N 20°E 32.22' PK nail west fa	uard rail post.																
C.	C. Description of monument for corner and accessories established to perpetuate locating the position of the corn											er:						
Set 5/8" iron with Oakland County Remonumentation Brass Cap stamped #24598 in new monument b										X , 1		Y						
	Set Witnesses:										-	R						
	South 19.55' Mag nail with OG S 45°E 26.13' Mag nail with OR N 30°E 32.22' Mag nail with OR 10°W 33.94' Mag nail with G	DCRT #24598 atc DCRT #24598 we	op guard rail post. est face MBT pole.		The second second		SIN P	JOS JOS JOS JOS JOS JOS JOS JOS JOS JOS	EPI SLC	ICH CON ZAK ONAL OR								
		,			1		D.P.	RFE	3101	III. S								

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871 REVISED MAY 14, 1975 REVISED JAN., 1983

Date_