For corners in

Oakland

1. Public Land Survey

2. Property Controlling

in Section

4. Lot No.

3. Miscellaneous

5. Private Claims

on this certificate.

Wampler, D.S.

Witnesses:

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 197d IRER 19827 PAGE
17.00 MISC RECORDING 126750 \$2.00 REMONUMENTATION
04/13/1999 01:46:39 P.M. RECEIPT# 18471
PAID RECORDED - GAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEED! Pontiac .. Located in: Twp. Corner Code # B-5 T_3NR_10R B-5Compliance with ACT 345, P.A. 1990 3-24-99 R APPROVED ON: OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number SECTION _, Recorded Plat 3 Raymond J. McCoy in a field survey on Mar. 7, 19 99 do hereby state that under conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 6 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 7 recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 11 12 OF MICHIGANINA A. Description of original monument and accessories and/or subsequent restoration: STATE OF MICHIGA Set Post There is one L.C.R.C. recorded. 1) 1998- J. Redash, Found 1/2" iron in Tree right-of-way. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" rod, 750'+/- West of Ernest Dr., Found an additional 1/2" rod 0.52' North. Located corner from witnesses in the above L.C.R.C. and in McCoy Survey (1995). Validated corner with subsequent divisions of Hahn Survey (1940) by McCoy(1995) and "WALTON SUBDIVISION"(L.88, Pg. 14, 1956) measuring closely to Hahn's original dimensions for the division of part of the S.E. 1 of Section 7. The found iron pipes shown in the McCoy Survey fit the Southerly iron. No support can be found for the Northerly re-rod. Sate Plane Coordinates N 430525.8645 E13404715.9121 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Replace the Southerly found 1/2" iron with a concrete monument consisting of a 1/2" iron rod encased in a 4" diameter concrete cylinder 36" long with a 2" diameter brass disk stamped Oakland County Remonumentation P.S. #21270. Due West, 6.33 Set O.C.R.T. #21270 S. face of 10" Cherry.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. Signed by Surveyor's Michigan License No.

N 5° W, 8.13' Set O.C.R.T. #21270 S.W. face of 8" Cherry.
S 88° E, 16.65' Set O.C.R.T. #21270 N. face 12" Oak.
Due South, 13.35' Set O.C.R.T. #21270 E. face twin 10" Oak.