MAY 1 6 1996

LIBER 15305rc 849

COMMISSION

LAND CORNER RECORDATION CERTIFICATE



COLDERS	

	(County)	Located In	n: Corner Code ##	
1.	Public Land Survey	T 4N	R <u>9E K-8</u>	
		T	R	
		Τ	R	
		Т	R	
2.	Property Controlling	S T	R	
	in Section	S T	R	
3.	Miscellaneous	S T	R	
	Property in Sec.	S T	R	

Filing Requirement of Act 74, Mich. P.A. 1970 7.00 NISCELLANEOUS RECORDING

\$ 2.00 REHONUMENTATION

23 MAR 95 9:49 A.M. RECEIPT# 14B PAID RECORDED - DAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with ACT 345, P.A. 1990

2-15-95 APPROVED ON: OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. __ _ , Recorded Plat _ 5. Private Claims _

James J. Scharl , in a field survey on December 15 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10
- Description of original monument and accessories and/or subsequent restoration:
- 3" B. Oak stood at the corner in 1817 G.L.O. survey.

Land corner recordation certificates recorded in L6156, P678; L6596, P835; L10471, P406, O.C. Records and O.C.R.C. section corner ties Ref No 95, were rejected in establishing the location of this corner. These documents all reference a 1/2" rerod 2.29 ft north of a 1/2" iron pipe accepted as the location of the section corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered a $1/2^{\prime\prime}$ iron pipe below the gravel surface of the Clintonville Road centerline. This corner checks well with monumentation recovered on section line to south, referencing Sashabaw Creek Farms, L92, P10, O.C. Records, and other record parcels.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod with 0.C. remonumentation brass cap, replacing 1/2" iron pipe.

19843

34.44' PK/remon tag N face 16" Oak West

N 45°W 49.55' PK/remon tag E face Oak cluster

33.20' PK/remon tag N face 12" Elm N 75°E

43.00' PK/remon tag N face 12" Pine

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

Signed by .

Date __ February 6, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983