Mar 2395047311

MAY 1 6 1996

2

LIBER 15305m855

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

60	PY
----	----

Fo	r comers in		-	\$ '	7,00	HISC	LLAN	EOUS	RECOR	DING		
Oakland (County)		Located In:	Corner Code ##		\$ 2.00 REHONUMENTATION 23 MAR 95 9:30 A.M. RECEIPT# 14B							
1.	Public Land Survey	T <u>4N</u> R <u>9E</u> T R T R T R		PA Lyi	PAID RECORDED - CAKLAND C LYNN D. ALLEN, CLERK/REGISTER OF Compliance with ACT 345, P.A. 1990 APPROVED ON: \$\sigma -15-95\$				COU	YTHUC		
2.	Property Controlling in Section	S T R S T R			KLAN.	D CO	JNTY	REM		IENT.	ATI(N
3.	Miscellaneous Property in Sec.	S T R S T R		Regis							nbei	-
		Recorded Plat			A	ВС	D E	F	G H	<u> </u>	J K	L I
5.	Private Claims			,T.A.T.	2	 	- 5 	- -	3 3	+	<u></u>	- -
	7 0 1 1	Day		ı.	4	?	8	-9-	-10	丰	, 	-12-
do in	hereby certify that under red	, in a field survey on	of 1970, the corner points ment id rules therefore as required	ioned in the	5 — 1 7 — 1	8	-17	— - —16—	15	\pm		—
Ma ab	anagement or by a decree of ove were in conformance wi	uctions of the United States Depart a Court of Lawand/or that the corne th the rules of the Michigan Board o	er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	and 5 se of a	81	9	20	-21-	22		23	_2 4 _
в×	pressed below:	re-established, monumented, re-r			10	10-	29	28	27		26	25-
N	OTE: Not more than 4 c	corners, all in the same town ar	nd range, may be recorded	F	11 —	+	╂╼┨		++	+	+	\dashv

A. Description of original monument and accessories and/or subsequent restoration:

• ••					
	Post set in 18	17 G.L.O. s	survey; N 26°W 103 1ks	30" W Oak; N 60°E 94	lks 14" W Oak.
	O.C.R.C.		LCRC, L6432, P374	LCRC, L7300, P642	LCRC, L14487, P080
	1967		Hendersen, 1974	Stonerock, 1978	Hart, 1993
			Fd 3/4" iron		Fd 3/4" iron bar, mon box
	WWN 36.76' Spk		*N30°W 51.03' NE cor		West 32.31' PK Box Elder
	SW 57.06' Spk		St. pillar	S28°W 56.47 Ctr St	*S35°W 54.71' nail St pillar
	-				N75°E 51.90' PK PP
	NE 42.51' Spk		St. pillar	N48°E 42.17 PK PP	*N35°W 50.74' 1" IP top
			N45°E 42.65 PP	Sil'E 21.10' Merge	stone pillar
				CION BOOK	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 3/4" iron bar in monument box at the intersection of extensions of Clarkston Road from the east and south, and Eston Road from the north. Box is located near the west edge of Eston Road.

Witnesses Found *N 35°W 51.18' NE cor stone pillar *S 35°W 54.38' NE cor stone pillar



REVISED MAY 14, 1975 REVISED JAN., 1983

*Confirms LCRC witness

on this certificate.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod with O.C. remonumentation brass cap in monument box, replacing 3/4" iron bar.

N 45°E 52.15' PK/remon tag S face DE pole 73.34' PK/remon tag N face 20" Elm M 80°W S 20°W 59.55' PK/remon tag NW face 10" Elm N 35°W 51.18' NE corner stone pillar

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

Signed by	2. Lumo	· Doul	Date February 2,	1995
Surveyor's Michigan Vice	ense No	108//3	FARM ARCONICO BY MICHIGAN ST	ATE BOARD OF LAND SHAVEYORS, JAN. 28, 1971