SUPVEY & REMONUMENTATION

MAY 1 6 1996

ز

HBFR 15305PG 857

LAND CORNER RECORDATION CERTIFICATE

For corpare	in COMMISSIO	N
For corners	in	

Filing Requirement of Act 74, Mich. P.A. 1970 1.00 NISCELLANEOUS RECORDING

OakTand (County)	Located In:	Corner Code ##		\$ 2.00 REMONUMENTATION 23 MAR 95 9:50 A.M. RECEIPT# 14B PAID RECORDED - DAKLAND COUNTY							
1. Public Land Survey	т <u>4N</u> в <u>9Е</u>	L-9	LYNN D. ALLEN, CLERK/REGISTER OF								
·	T R T R T R			A	Compl	iance w i, P.A.	ith 1990				
2. Property Controlling	S T R		APPROV	ED O	<u>ء ۔۔۔۔۔۔</u>	<u>2- /S</u>	<u> </u>				
in Section	S T R		OAKLAN)NUME: IMITTE		MON	i	
3. Miscellaneous			Registe						mbe	e r	
Property in Sec.	S T R						······································				-
4. Lot No	, Recorded Plat			A R	C D	E F	GН		1 K	1 6	•
				ÎŤ	ŤŤ	ŤŤ	"	Ť	Ĥ	<u> </u>	i
•			2	6	- -	┼-†-	- 3-	+	2-		
			3		+ +		++	+	\vdash	\vdash	1
		115 04	4		- 8-	- 	10-		ij	i2	1
	, in a field survey on <u>Dec</u> requirements of P.A. 74, Michigan P.A. c			\vdash	+	++	++	+-	+	\vdash	
	e in conformance with regulations and			18		16-	1/5-	+	14-	(3	
	structions of the United States Depart			\vdash	++	++	++	+-	+	-	1
-	of a Court of Law and/or that the corner with the rules of the Michigan Board of	= -		1 ¹ 9	20-	21	22	╬	23—	—2 4 4—	1
	I, re-established, monumented, re-m		41			+	++		┼╌┤		4
expressed below:		•	10	30-	29	28	27.	-∤	26-	<u> </u>	-
NOTE: Not more than 4	corners, all in the same town an	d range, may be recorded	11	_	++		$\dashv \dashv$		$\downarrow \downarrow \downarrow$	$\vdash \vdash$	1
on this certifica	te.		12	 31-	32-	33-		┵	35	-36-	4
			13	<u>L_i_</u>				丄	$oxed{oxed}$	$oldsymbol{oldsymbol{oldsymbol{eta}}}$	
A. Description of origin	al monument and accessories and	I/or subsequent restoration:									
Post set in 1817	G.L.O. survey; N 45°E 9	1ks, 12" Beech; S 64	°W 36 1	ks,	36"	W. P	ine.				

Jones, 1973, Found 1" iron pipe

- *N 40°W 29.98' 6" Maple *N 42°E 27.85' 6" Maple *S 40°W 22.98' 10" Maple
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered a 1" iron pipe on centerline of Waldon Road 14" below the gravel surface. A 1/2" rerod was also recovered 3.74 ft east of the pipe. The location of the 1/2" rerod was rejected through lack of supporting evidence.

Witnesses Found *N 40°E 27.37' PK/tag 17623 SE face 12" Triple Maple

*N 30°W 29.91' PK/tag 17623 S face 12" Maple *S 40°W 22.57' PK/tag 17623 NW face 16" Maple S 60°E 48.78' PK NE face 16" W. Pine



*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" rerod with 0.C. remonumentation brass cap, replacing 1" iron pipe.

N 40°E 27.37' PK/remon tag SE face Triple Maple

S 50°E 48.78' PK/remon tag NE face 16" W. Pine

22.58' PK/remon NW face 16" Maple S 40°W

29.90' PK/remon tag SW face 12" Maple

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

		. 5	7	0.20				
Signed by		Come)	\mathcal{U}	Crave	Date	February 7,	1995	
Surveyor's Mic	higan Licen	se No	19843	****		FORM APPROVED BY MICH	HIGAN STATE BOARD OF LAND SURVEYORS, JAN.	

ご機械組むがなり、

REVISED JAN., 1983