MAY - 1 1995

## LIBER 15175 Pt 148

DEC	299132 20 mpliance with 12:14	
	ACT 345, P.A. 1990	
	APPROVED ON:	

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE OAKLAND COUNTY EMONUMENTATI Filing Requirement of Act 74, Mich. P.A. 1970

PEER GROUP COMMITTEE

For corners in				
Oakland (County)	Located In: Brandon Corner Code ##	4 7.00 MISCELLANEOUS RECORDING \$ 2.00 REMONUMENTATION		
Public Land Survey	T <u>5N</u> R <u>9E</u> T R T R T R	M-9	29 DEC 94 9:47 A.M. RECEIPT# 468 PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R		OK - T. SMITH  Register of Deeds Stamp & File Number	
	ecorded Plat		A B C D E F G H I J K L	
Huston K. Kennedy do hereby certify that under requirement manual of survey instruct Management or by a decree of a above were in conformance with Court of Law; established, re expressed below:	in a field survey on	per 1, 1994 1970, the corner points mention rules therefore as required in the line of the Interior, Bureau of Larpoints mentioned in lines 3, 4 and Land Surveyors or by a Decree on unmented, recovered, found	he nd 7 19 20 21 22 23 24 sta	
1817-GLO Carpenter, D.S. 1.) 1977-Kennedy, P.S. #1 2.) 1987-Kennedy, P.S. #1 3.) 1976-Kennedy, P.S. #1 4.) 1983-Kennedy, P.S. #1	ionument and accessories and/ ; Set Post 12" White Oak S21 1/: 17623; LCRC L.7067, Pg.315 - Fno 17623; LCRC L.9859, Pg.847 - Fno 17623; Unrecorded Survey - Fnd 17623; Unrecorded Survey - Fnd	2°W 134 Links; 8" White Oak d 1" Iron in a Monument Box d 1/2" Iron Rod in a Monumer 1" Iron Rod in a Monument Bo 1" Iron Rod in a Monument Bo	S41°W 82 Links  nt Box  ox, used same wit as 1977 LCRC	

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Pipe in a Monument Box 1' East of the centerline of Baldwin Road which has a bituminous surface and Sherwood Road extending to the West, which has a gravel surface. The Southwest corner of Section 19 and the Northwest corner of Section 30, T5N, R10E, is located 549.82' to the South.

Witnesses from LCRC #1 & 2 were used to recover and verify the location of the found 1/2" Iron Pipe in a Monument Box.

I accept the found 1/2" Iron Pipe in a Monument Box as the best evidence of the original corner position.

5.) 1986-Kennedy, P.S. #17623; Unrecorded Survey - Fnd 1/2" Iron Rod in a Monument Box, used same wit as 1987 LCRC

## FIELD MEASUREMENTS BETWEEN

M-9 to L-9 2652.92 Ft. (H. Kennedy 1983) M-9 to M-8 2650.78 Ft. (H. Kennedy 1975)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-9 I replaced the found 1/2" Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation PS #17623 in a existing Monument Box.  $q = p_0^{A_1B_2}$ 

S71°W 77.98' Set PK & Remon. Washer North face 25" Haple

N72'W 75.71' Set PK & Remon. Washer South face 11" Maple N35'E 71.18' Set PK & Remon. Washer SE face Power Pole

N75'E 70.45' Set PK & Remon. Washer South face 19" Pine

South 549.82' Southwest corner of Section 19 and the Northwest corner of Section 30, T5N, R10Es

The selected location is accepted by me and is generally accepted by Professional Surveyors as position of the original corner.

Signed by Surveyor's Michigan License No

BAFESSION N OF WHITE WASHINGTON FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

OF MICHIG

HUSTON avk[] WED Evid

PROFESSIONAL SURVEYOR

17623