FEB 2 2 1996

## LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

**1**00627

JUL 10 P2:47 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code ## oceana County E. Francisco REGISTER OF DEEDS T\_13\_R\_18 H-7 1. Public Land Survey . R \_ T \_\_\_\_\_ R \_ **Property Controlling** \_ T \_\_ In Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_\_\_ , Recorded Plat \_ 5. Private Claims ...June 12 I J. Randloch Hapworth , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration:
H-7 1/4 Corner Common to Sections 15 and 22 T13N, R T13N, R18W CLAYBANKS TOWNSHIP 10" Reach S10°F 23.1" GLO 18" Pine N14°F 284' "Old stake and witness stump standing. Drove new post." Book A. Pa 138: S Edson, 1883: Book A, Pg 330; HA Grant, 1893; "Stake previosly set by E. Hyde 6" Beech S38°W 5,9" B. Description of corner evidence found and/or method applied in restoring or reestablishing corner I found a 1 1/2" Pipe well-rotted at ground level and projecting 8" above ground. An old barb-wire fence was found to run east from this corner and an old barb-wire fence was found to run south from this corner at 33' easterly of the corner. No occupation is visible or found to the west. A north-south 2-track trail is east 11'. After excavation and removal of the Pipe, further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the position of the corner. The Found 1 1/2" Pipe is accepted as a careful and faithful perpetuation of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. 1/4 Corner Common to Sections 15 and 22 T13N, R18W CLAYBANKS TOWNSHIP Set "COUNTY SURVEYOR" HARRISON 4"X20" cast iron Monument above the found 1 1/2" pipe which was driven down. EDM 60d spk S Face 12" R Oak 64°az 31,83 60d spk SW Face 10" R Oak 147°az 60.30 **EDM** 60d spk NW Face 31.88 8" Beech 240°az **EDM** 60d spk NE Face 10" tw R Oak 337°az < 17.89 Oceana County Remonumentation Peer Group Reviewed & Approved 5-25-95 J. Randolph Hepworth Qpeana County Surveyor J. RANDOLPH FORM APPROVED BY MICHIGAN STATE BOAM APPROVED BY MICHIGAN STATE BY MICHIGAN STATE BOAM APPROVED BY MICHIGAN BY

Date

Signed by

Surveyor's Michigan License No. .