Oceana County Remonumentation -Peer Group Reviewed & Approved

5-25-95 TRH

J. Randolph Hepworth

Oceana County Surveyor For corners in

FEB 2 2 1996

MOISSIMMOS

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHERAN COUNTY OF OCEANA MECHIVED FOR BEFORE

100619 JL 10 P2:46

Ju.	magent.	£.	me	e inci
9	REGISTER OF DEEDS			

Register of Deeds Stamp & File Number

	Oceana (County)	Located In:	Corner Code ##
1.	Public Land Survey	T 14N R 16W	F-7
••		T R	
		<u>T</u> <u>B</u>	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	\$ T R	
	Property in Sec.	S T R	

___, Recorded Plat _ 4. Lot No. 5. Private Claims _

J. Randolph Hepworth

June 14, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior; Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1/4 Corner Common to Sections 16 and 21 F-7

T14N, R16W FERRY TOWNSHIP

GLO

18" Elm S10°E 11.9"

6" Birch N51 1/2°W 16.5'

Book A, Pg 44; S. Edson, 1879;

Set Post 12" Hemlock S20°E 19.8'

Hemiock S12°W 32.3° No witnesses recited

Book A, Pg 426; HA Grant, 1896;

Iron bar 1 1/2 "x 1/4"x 47"

OCRC WITNESS: 1962, iron OCRC Witnesses added 4-18-68 Spike in 3" Cedar S60°E 86.2' S80°E 82.60 T. Cedar

Spike in 24" Eim Due East 45.4 Cedar S75°E

T.P.

Unrecorded survey, Dunlap, PS21759; 5-18-81; Corner not described or witnessed

Unrecorded survey, Hepworth, PS21759, 12-3-84; Found 1/2" Iron, NDAI, 16345

Rd Name Sign 241°az 32.0 Stop Sign 90°az 34.15

8" Tamarack 15°az 158.85

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

I found a 1/2" from in the surface of an asphalt road that is known to me to have had a NDAI cap in 1984. The Iron is located in the C/L of a N-S asphalt road; C/L of gravel road to the west; and, 10' north of C/L of gravel road to the east.

All 1962 OCRC witnesses are gone. The T. Cedar of the 1968 OCRC witness, I believe, refers to the 6" triple Cedar stump that I found at S80°E 82.8' to the face. The OCRC witness to a TP (telephone Pole) is missing; however, a Tel Junction Box is within 3 feet of the recited distance to the pole which is consistent with the placement of Junction Boxes beside Poles. The corner position falls in a road intersection of about 5 feet of fill above original ground level of the swamp hole.

Upon an inquiry to the office of Nordlund & Associates, I was informed that this corner was set from the local evidence of the centerline of the north-south-west roads and the remaining OCRC witness.

Further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available The Found 1/2" Iron is accepted as a careful and faithful perpetuation of the position of the evidence for the position of the corner. original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

1/4 Corner Common to Sections 16 and 21

T14N, R16W

FERRY TOWNSHIP

Set "COUNTY SURVEYOR" HARRISON 4"X20" cast iron Monument above the found 1/2" Iron which was driven down.

76°az 61.8 Telephone Junction Box tape center clp 10" Cedar 69°az 60d spk N Face 101.02 FOM **EDM** 60d spk N Face tw 12" Maple 109°az 127.59 EDM S Face 12" Maple 286°az 123.05 60d spk 158.84 13°az W Face 10" Tamarack

July 6, 1995 Date

J. RANDOLPH HEPWORTH

REVISED JAN., 1983

Surveyor's Michigan License No. __