SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

TATE OF MICHGAN COUNTY OF GCEANA RECEIVED FOR BECSEN

JAN -4 P3:25

For corners in			
Oceana	Located In:	Corner Code ##	
(County)			
Public Land Survey	T 14N R 17W	C-4	
	T R		
	T R		
	T D		

Allacare. REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	(County)	Located In:	Corner Code ##
1.	Public Land Survey	т <u>14N</u> R <u>17W</u>	C-4
		T R T R	
		T R	
2.	Property Controlling in Section	S T R S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

_, , Recorded Plat Lot No. Private Claims ...


J. Randolph Hepworth

September 30

94

, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

1/4 CORNER COMMON TO SECTIONS 7 AND 8

T14N, R17W

SHELBY TOWNSHIP

GLO SET POST 8" Beech N18°E 11.9"

10" Elm N89°W 19.8

Book A, Pg 56; S. Edson, 1879; "some RR Iron" 20" Elm N78°E 27.1

OCRC WITNESS: 1949 1/2" Iron

Cor. fence post due East 33.0

Jkt 300; D. Dunlap, 21759, Nordlund, Dunlap, Inc; 11-26-80; Corner not described or witnessed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

I found a 1/2" Pipe in the surface and center of a north-south asphalt road and center of gravel road to west and old occupation line to east. Upon excavation, I found this to be a 1/2" x 12" Pipe and to be above driven over a 1/2"x 24" Iron. Excavated to 36" below surface of asphalt through extremely well-compacted gravel material. An iron object could be detected within the center of the excavated hole.

Further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the The Found 1/2" Pipe over the 1/2" Iron are ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE position of the corner. POSITION OF THE ORGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set "County Surveyor" HARRISON cast iron 4"x20" monument above the 1/2" Pipe and 1/2" Iron

the pipe and iron were driven down.								
60d spk	SE Face	P ower Pole	212°az	251.26	EDM			
60d spk	E Face	Power Pole	186°az	205.00	EDM			
60d spk	NE Face	Guy Pole	173°az	204.34	EDM			
60d spk	S Face	Power Pole	107°az	386.00	EDM			
60d spk	SW Face	Power Pole	297°az	69.97	EDM			
60d spk	NE Face	18" Maple	342°az	79.88	EDM			
60d spk	E Face	Telephone Pole	6°az	272.67	EDM			

26457

EARDOUNI HEPWORTH SURVEYOR

Oceana County Remonumentation Peer Group Reviewed & Approved

94

J. Randolph Hepworth Oceana County Surveyor

Signed by

Surveyor's Michigan License No.

Date

December 28,

1994