Oceana County Remonumentation STATE OF MICHIGAN COUNTY OF GCEANA Peer Group Reviewed & Approved 525-95 TFR 2 2 1995 RECEIVED FOR PERCORD **#** LAND CORNER RECORDATION CERTIFICATE 100650Randolph Hepworth Oceana County Surveyor For corners in Filing Requirement of Act 74, Mich. P.A. 1970 JUL 10 P2:49 Oceana County Located In: Corner Code ## E. Maciena REGISTER OF DEEDS 1. Public Land Survey T_14_R_18 _____ R ___ _ R ⁻ __ R . 2. Property Controlling Τ_ ___ R __ in Section _ T _____ R ___ Miscellaneous _ T .____ R ...__ Register of Deeds Stamp & File Number Property in Sec. ___ , Recorded Plat ___ Private Claims 2 3 I.J. Rambligh Hapworth , in a field survey on ______ June 12______, 19 $_$ g g do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. Description of original monument and accessories and/or subsequent restoration: G-13 Corner Common to Sections 33 and 34 T14N, R18W BENONA TOWNSHIP Set Post GLO 10" Beech N62°W 18.5' 14" Beech N17°E 32.3' Book A, pg 274; HA Grant, 1891; Found stone previously set for govt corner; No witnesses recited. Book C, pg 142; EM Hyde, 1910; corner not described/ witnessed or measured to. LCRC 100253; Hepworth, PS26457; 2-18-80; Set 3/4" Iron on east-west fence, T13N,R18W corner (G-1). set by projecting line westerly from a found concrete monument at 1/16 corner & from the N 1/4 corner of Section 3,T13N,R18W and doubling the distance. 24" MapleN65°E 9.12 12" Maple N30°E 57.5 28" Basswood N70°W 16.22 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner I found the Hepworth 3/4" Iron as described by LCRC100253. Upon traversing from I-13 to (H-1, T13N) to this position and also measuring to a concrete monument set by CM Stover at the west 1/16 corner on the section line, I decided this corner position needed to be reconsidered. This corner position falls in an old east-west fence (lying down) with no occupation lines north or south. The fence line is scattered with numerous rocks and stones so a search for the Grant, 1891 stone would be fruitless. A survey was done in the NW 1/4 of Section 3, T13N, R18W by CM Stover which was based on the concrete monument. However, I believe that Stover set that monument by occupation lines E & N at that 1/16 corner and did not recognize that double corners exist along the township line. The Concrete monument does fit those occupation lines. Also, measurement westerly from I-13 to the concrete monument fits very closely the Grant, 1891 survey measurement of 3963.9 feet compared with JRH measurement of 3963.51 feet. If the conc. monument is recognized as more correctly showing the 1/16 corner for Section 34 and not Section 3, then the corner position at H-1 for T13N also fits within 2.7 feet of a strict single proportion between I-13 and the resulting position of G-13. If the concrete monument is accepted as the 1/16 corner for Section 3, then measurements along the south section line do not fit Grant, 1891 measurements nor will the corner established at H-1 in LCRC100253 fit the GLO proration but would then fail at point 13.0' east of the position in LCRC100253 and would not fit the local evidence of centerline of existing roads at H-1 (H-13). After considering all these factors, I have concluded that G-1 in LCRC100253 set by Hepworth is not in the best location, but should in fact be 20.56 feet further west and that G-13 corner should be 11.88 feet (GLO distance) east of that position. Therefore, I set a 1/2"x24" iron/cap for a temporary marker. The 3/4" Iron (G-1) of LCRC100253 was pulled and discarded by me. Further search of the area failed to yield any other evidence for a conflicting position for the corner. This represents the best available evidence for the position of the corner. This position is accepted as a careful and falthful re-establishment of the position of the original comer. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-13 Corner Common to Sections 33 and 34 T14N, R18W BENONA TOWNSHIP

Set "COUNTY SURVEYOR" HARRISON 4"X20" cast iron Monument in place of the temporary 1/2" Iron 16" Basswood 19°az 49.18 EDM 60d spk NE Face 18" Basswood 327°az 46.25 **EDM** 60d spk 60d spk S Face S Face 28" Basswood 299°az 7.16 14" Beech 287°az 55.32 FÓM T13N, R18W corner West 11.88 tape LCRC100253 corner (pulled & discarded) 8.68 tape I RANDOUPH HEPWORTH LAND Signed by Date . SURVEYOR NO. -Surveyor's Michigan License No. 26457

FORM APPROVED BY MICHIGARYSTATE BOARD OF TAND SURVEYORS: 147 28, 1971

FOR LAND REVISED JAN., 1983