SURVEY & REMONUMENTATION

OCT 27 1993

COMMISSION

COUNTY REMONUMENTATION **OCEANA** LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

100503

OCT -7 P2:45

| For corners in | ì |
|----------------|---|
|----------------|---|

| | (County) | Located In: | Corner Code ## | |
|----|----------------------|-------------|----------------|--|
| 1. | Public Land Survey | T14N R18W | I-13 | |
| | i. | T R | | |
| | | T R | | |
| | | T R | | |
| 2. | Property Controlling | S T R | | |
| | in Section | S T R | <u> </u> | |
| 3. | Miscellaneous | S T R | | |
| | Proporty in Soc | e T p | | |

L. E. meitino REGISTER OF DEEDS

Register of Deeds Stamp & File Number

3

10

11

| ╼. | Lot No , necorded Flat |
|----|------------------------|
| 5. | Private Claims |
| | |

J. Randolph Hepworth September 30, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

Description of original monument and accessories and/or subsequent restoration:

CORNER COMMON TO SECTIONS 34 and 35; BENONA TWP; T14N, R18W 18" BEECH GLO SET POST 24" BEECH N36°W 28.41 N740E 28.41 BOOK A-224 HYDE, 1889 SET STOKE AT GLO POSITION BOOK A-274 GRANT, 1891 STONE PREVIOUSLY SET AT GLO CORNER BOOK A-276 GRANT, 1891 SAME OCRC WITHESS: PLOW POINT 20" MAPLE 8450W 38.0; TEL POLE \$250E 51.81 LCRC \$100245 J CAMPBELL, PS 15397 FOUND PLOW POINT RAISED W/ 1/2ª IRON P POLE SEOR 67.2 TEL BOX . N60E 53.B

B.Description of corner evidence found and/or method applied in restoring or reestablishing corner

58.8

FOUND 1/2" IRON AT + ROAD INTERSECTION E-W & N-S AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I-13 CORNER COMMON TO SECTIONS 34 & 35, T14N, R18W

STOP SIGN H30W

SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT IN PLACE OF FOUND 1/2" IRON on top of plow point

| 16d SPK | E FACE | POWER POLE | 830°W | | 63.81' | TAPED |
|---------|---------|-------------|-------|--------------------|--------|---------------------|
| 16d SPK | | POWER POLE- | S30°E | | 74.281 | TAPED |
| 60d SPK | W FACE: | BA HAPLE | N30°B | **** | 52.381 | . · . yes to TAPED: |
| CENTER | | STOP SIGN | N20°W | 2 - 1 - 1 1 - 1 | 54.51 | TAPED |
| ٠. | | | , | | | |



Surveyor's Michigan License No. 26457

October 6, 1993 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

11.5-93

REVISED JAN., 1983