SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RESERVED FOR PRICERS

100582 95 JAN-4 P3:24

0.00		-			
	eana	Located In:	Corner Code =##	\mathcal{Q}	my E Trends
	(County)				REGISTER OF DEEDS
1 Duk	olic Land Survey	T 14N R 18W	K-13	•	UCAMO LEM OL MECHO
I, FUL	Jilo Lana Guivey	T R			
					·
		T R			•
		T R			And the second s
	perty Controlling	S T R			
in S	Section	S T R			
3. Mis	cellaneous	S R		Register of Dee	ds Stamp & File Number
Pro	perty in Sec.	S T R			
4. Lot	No	, Recorded Plat		A B C	DEFGHIJK
5. Priv	/ate Claims				
				2 - 6	- 5
				3	
J.	Randolph	Hepworth		4 7	- 8 10 11
,	Manaorph		ember 13 to 94		ĭ l ĭ l ĭ l ï l
do herel	by cortify that under	requirements of P.A. 74, Michigan P.A	of 1970, the corner points mentic	nad	
		e in conformance with regulations a			-17161514
		structions of the United States Depa			
		of a Court of Law and/or that the corn			-20 -21 -22 -23 -
		with the rules of the Michigan Board			
		d, re-established, monumented, re-	-monumented, recovered, found	as 10 30	
•	ed below:			T Y	-29 + 28 + 27 + 26 +
NOTE:	Not more than 4	4 corners, all in the same town a	and range, may be recorded	11	- - - - - - -
	on this certifica	te.		12 31	-32333435
				13	
	GLO SET POST BOOK A-66 EDS	VER COMMON TO SECTIONS 18" Beech N37°E 29.7' ON, 1880 Stone 16"X24"X15" DE, 1889 Stone previously set	14" Elm N08°E 13.	Pear G.d	County Remonumentation approved 12-1-94
		RANT, 1891 same			1RH
	OCRC WITNESS:	: 1/2" IRON 12" Elm S20°E 42.5' 4	"Pine S50°E 47.6"		<u></u>
	LCRC #100244 J CAMPBELL, PS 15397; June 27, 1979; Set 10" Spike in Pvmt NW Cor Hse SE 83.85 P Pole S50"W 80.27 St Sign				liph Hepworth County Surveyor 8. 37
	B. Description No ancient eviden itself.	of corner evidence found and/once was found at this corner. Extensi	r method applied in restoring ve road construction has destroyed	or reestablishing co all evidence, except for	rner the road intersection
	In August, 1983, I established this or measurements the Road Re-construc- documented and the was 4.97' North as	I found the Campbell corner per LCRC orner erroneously after this position was at he had from a J. Clapp (working for ction. Apparently, Campbell (working found by his company several years earned 12.98' West of the position re-estable.	is destroyed by Road Construction. Kistler & Assoc.) survey in the ear of for Kistler & Assoc.) had not set the arlier. I removed the Campbell co- lished by Sandel.	Sandel re-established ly 1970's, date unknown his corner at the same to orner in 1984. The For	the corner based on that was prior to the scation as had been und Campbell 10" spike
	The found 1/2" PII POSITION OF TH utilized in this Sur	PE established by D. Sandel, PS 258 HE ORIGINAL CORNER. The Campb rvey.	70 IS ACCEPTED AS A CAREFUL pell corner, LCRC 100244, was est	. AND FAITHFUL PERP ablished using improper	ETUATION OF THE procedures and is not
	C. Description	of monument for corner and ac	cessories established to perpo	etuate locating the p	osition of the corner.
-		NER COMMON TO SECTIONS NER COMMON TO SECTIONS	•		v P
	SET FOOLINGS S	URVEYOR" HARRISON 4"X20" CAST	IRON MONIMENT on top of the	1/2" Pipe which I drove o	down.
	60d Spk E Face		S80°W	89.34' TAI	PED
	60d Spk N Face	="	\$70°E		PED
	NW COR. House		SE	,	PED
	NE COR. Church		SW	125.8' TA	PED

Signed by

Surveyor's Michigan License No. _

_--

N20°E

N70°W

Stop Sign
Spike LCRC1000244 (pulled & discarded in 1984)

26457

Date December 28,

58.10

13.90

1994

TAPED

TAPED

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983