SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE 0	F MICHIGAN OF OCEANA FEP RECORD
COUNTY	OF OCEANA.
RECEIVED.	hills showing

100583

JUN -4 P3:24

	eana (County)	Located In:	Corner Code =##	Quyen &	The state of the s
1. Pu	blic Land Survey	T <u>14N</u> R <u>18</u> T R T R	-	REGISTER (OF DEEDS
in 3. Mi	operty Controlling Section scellaneous operty in Sec.	T R S T R S T R S T R		Register of Deeds Stamp	& File Number
				— A B C D E F	GHIJKL
J. do here in lines curren Manag above	Randolph He eby certify that under re s 1 and 2 above were t manual of survey instement or by a decree of were in conformance w of Law; established, sed below:	epworth Dina field survey on Dina field survey on Dina field survey on Dina field survey on Dina fin conformance with regulations ructions of the United States Defa Court of Law and/or that the confith the rules of the Michigan Boare-established, monumented, Corners, all in the same tower.		The and 7 dd 5 8 19 20 21 of a	-10 -11 12 15 14 13 22 23 24 27 26 25 34 35 36
A. D	L-13 S 1/4 C L-1 N 1/4 C GLO SET POST BOOK A-66 EDSOI OCRC WITNESS: 5" Ash	CORNER TO SECTION 36 ORNER TO SECTION 1 20" Hemlock N81°E N, 1880 Stone 5X6X18; GLO Will Stone & Axle; 20" Maple S N30°E 26.49 ampbell, PS 15397 N 1/4 COR S		WP 13.9' uth 72.2' 5" Ash S22°W	40.35
	No ancient evidence itself. I found a 1/ In May 1984, D San was destroyed by R Kistler & Assoc.) st the same location a corner in 1984. The found 1/2" PIPE	e was found at this corner. Exter 2" pipe in the surface of the cente del, PS25870, informed me that Coad Construction. Sandel re-estaurvey in the early 1970's, date unks had been documented and found established by D. Sandel, PS 20 ORIGINAL CORNER. The Can	for method applied in restoring of the sive road construction has destroyed a rline intersection of an east-west asphaticampbell per LCRC100244 had re-established the corner based on measurer known. Apparently, Campbell (workind by his company several years earlier the same of the	all evidence, except for the road intal road and gravel road to the sout oblished this corner erroneously after ments that he had from a J. Clapping for Kistler & Assoc.) had not set a Sandel pulled and discarded the AND FAITHFUL PERPETUATION.	th. er this position (working for this corner at a Campbell OF THE

SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT on top of 1/2" pipe which had been driven down

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

CENTER	Road Nan	ne Sian N40°E	32.5'	TAPEC
WEDGE	Stop Sign		60.70'	TAPED
60d Spk N			102.92'	TAPED
60d Spk N		E \$80°W	177.52'	EDM
16d Spk W	/ Face Power Po		333.53'	EDM
Campbell 10	0" Spike LCRC1000244 (pu	illed & discarded in 1984 by	Sandel) N13°W 2.46	TAPED

S 1/4 CORNER TO SECTION 36 T14N, R18W BENONA TWP N 1/4 CORNER TO SECTION 1 T13N, R18W CLAYBANKS TWP

Oceana County Remonumentation Peer Group Reviewed & Approved

1-94

J. Randolph Hepworth Oceana County Surveyor

Date _ December

Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983