JAN 1 1 1999

SECTION

100851

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

28 DEC 1998 4:31:27 PM

For corners in			1					
Oceana	Located In:	Corner Code	#			. MERTEN	_	
(County)	1 5 11	.16W D-5			REGISTE	of Deens	3	
1. Public Land Survey	† <u>15N</u> R							
*E	TR TR							
2. Property Controlling	s TR							
in Section 3. Miscellaneous	s— i— r							
Property in Sec.	S TR			Regi	ster of Deeds	Stamp & F	File Numb	er
4. Lot No, Recor	rded Plat			А В	CDEF	G H I	jĸ	L
5. Private Claims				1	ŤĪĪĪ		Ţ	Ţ
				2 6-	5-1-4			Ĺ
T Bandalph Henwort	h I	April 24, 199	8	3		10		12
J. Randolph Hepworth in a field survey on 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in								1
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or United States Department of the Interior States of the Michigan			or 6 -18-	17 16	15	14	 13	
			** _ i		_}_		+	
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumer recovered, found as expressed below:		c-established, monani-	8 -19-	2021	22	23	24	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9	- - - - 		-	†	
				1030-	2926	27-	-26	25
				11	- - - -			1
				12 31	32 33	34	35	36
A. Description of original mo	onument and accesso	ories and/or subseque	ent restoration:	1311-	Oceana Cou Peer Group			
D-5 1/4 CORNER COM	MON TO SECTIONS 8				Date:	10 -13	- 98	, u
GLO SET POST 4" Lyni	n N57°E 22.4'	12" Beech	S40°W 11.2'		Date:	124		-
BOOK A, PG 78; S EDSO	N, 1880; Gov't come	r standing: Gov't witn	esses standing	·	J. Randolph	Hepworth		
OCRC WITNESS: Undate NE Corner of Ba 10" Elm NNW	d, 3/4" Iron Rod T rn 93.6' (no direction r 25.95	ecited) T	P N70°E 92.2 Pole N20°W 23.5 42.90	30" Elm N	§2c•ana Cou	nty Survey	vor .	
B. Description of corn	er evidence found ar	nd/or method applied	d in restoring or reestal	blishing corr	er			
I found an Engine Valve ju- iron was also found to be 1 witnesses are standing. evidence of the position of	I,55' N and 1.40' W of a I believe that this 3/4" I the original corner. C	ron is the same as with forner is in the center o	essed by the OCRC. The fan east-west road	ne found 1/2" d and center o	ron is not accep f gravel road so	nted as the louth	best	
The 3/4" iron is accepted construction purposes. At	fter new road grade was	s established, conter a	is originally lourid to count			_	†or	
C. Description of mor	nument for corner a	nd accessories establ	lished to perpetuate loc	ating the po	sition of the co	orner.		

D-5 1/4 CORNER COMMON TO SECTIONS 8 and 17 ELBRIDGE TWP; T15N, R16W
Set "County Surveyor" Harrison 4"x20" cast iron monument, stamped "County Surveyor" and "26457" from remaining construction witnesses at a level about 6 feet higher than in 1994.

set 1/2" Iron set 1/2" Iron set 1/2" Iron set 1/2" Iron notch in end of CMP 113.57 102.52 105.82 EDM 219°az EDM EDM EDM 303°az 43°az 356,27 77.04 71.42 south EDM 306°az 241°az 115°az **EDM** notch in end of CMP notch in end of CMP notch in end of CMP EDM 77.67 85.29 **EDM** I. RANDOLPH
HEPWORTH
LAND
SURVEYOR
NO.
26457
AED LAND

Signed by Male Agree 18	November 10, 1998
Surveyor's Michigan License No. 26457	