JAN 11 1999

SECTION

For corners in

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF NICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

28 DEC 1998 4:27:55 PM

JOSEPH E. MERTEN REGISTER OF DEEDS

Oceana Located In: Corner Code # 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous

Register of Deeds Stamp & File Number

Property in Sec.	S TR	
4. Lot No Re 5. Private Claims	corded Plat	
United States Department of that the corner points mention	APTIL 17, 1998	of the nd /or

8 9 10 11 12

A. Description of original monument and accessories and/or subsequent restoration: F-5 1/4 CORNER COMMON TO SECTIONS 9 AND 16 T15N, R17W HART TOWNSHIP

SET POST 10" Elm N32°E 12" Beech 9.2 OCRC WITNESS BOOK Pre-1950 Iron pipe 12" Elm N1กจพ 23.8' 10" Elm N50°E 52.9 N. W. Cor. of house 73.15 S. W. Cor. of house S. E. Cor of Dry cleaners 46.20 TP 31.0 S15°E Right of Way Map, Cceana Dr., File No. 64-R-2, Sheet 10
Recorded Survey, Jkt # 253, James T. Nordlund 16345, 8-6-79 No info given Recorded Survey, Jkt # 321, J. R. Hepworth 26457, 8-1-81, Fd R.R. Spike Recorded Survey, Jkt # 322, J. R. Hepworth 26457, 8-11-81, Fd R.R. Spike

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

Oceana County Remonumentation Peer Group Reviewed & Approved

13-98 ILA J. Randolph Hepworth

LCRC 100772; Hepworth, 12-1-97 Found R/R Spike c/l E-W Road & old fence to North c/I E-W Roa SW Cor, Brick Bldg SE Cor, Brick Bldg 15ºaz 42ºaz 46.18 Power Pole 306°az 74.70 Telephone Pole 194ºaz

on this certificate.

Oceana County Surveyor

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found RR Spike in the surface and on centerline of E-W Road and old occupation line to North; no occupation is visible to the south. Corner falls in area of 4'± fill. 3 OCRC witnesses are standing and measure OK, except the existing Tel. Pole is S16°W not S15°E, OCRC distance is to the face. Also, the SW corner of the House at 37.75' is referring to the brick bldg, not a house. Upon excavation and removal of the RR spike to 20" deep, I could detect an iron object below and centered in the excavated hole. I decided further excavation to be un-necessary.

I accept the 1/2"x34" iron and wood fragments as a careful and faithful perpetuation of the position of the original corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457"; the RR spike was given to the adjoining landowner. 60d spk **NW Face** Power Pole 70°az 75.44 **EDM** 60d spk N Face Tel. Pole 112ºaz 112.87 **EDM** 60d spk E Face Tel. Pole 198°az 31.35 **EDM** 60d spk S Face Power Pole 293°az 92.24 **EDM** SW corner of Brick Building 15ºaz 37.43 **FDM** SE corner of Brick Building 46.20 **EDM** NW corner of House Foundation 158°az 73.05

HEPWORTH LAND SURVEYOR NO. November 10, 26457

Signed by 26457 Surveyor's Michigan License No.

Date

E of MICHIGH

J. PANDOLPH