SURVEY & REMONUMENTATION

JAN 1 1 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

100832

STATE OF MICHIGAN COUNTY OF OCEAHA RECEIVED FOR RECORD

28 DEC 1998 4:28:12 PM

For corners in Oceana	Located in: Corner Code #	JOSEPH E. MERTEN REGISTER OF DEEDS
(County) 1. Public Land Survey	15N 17W F-11 T_R	REGISTER OF DELEGA
Property Controlling in Section Miscellaneous Property in Sec.	T_R	Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat	A B C D E F G H I J K L I 2 - 6 - 5 - 4 - 3 - 2 - 1 -
J. Randolph Hepwor: I, requirements of P.A. 74, Michig conformance with regulations and United States Department of the that the corner points mentioner Board of Land Surveyors or be recovered, found as expressed by	th May 15, 1998 in a field survey on 19 do hereby state that und an P.A. of 1970, the corner points mentioned in lines 1 and 2 above were ad rules therefore as required in the current manual of survey instructions of a linterior, Bureau of Land Management or by a decree of a Court of Law and d in lines 3, 4 and 5 above were in conformance with the rules of the Michigay a Decree of a Court of Law; established, re-established, monument	ian 6 18 1
F-11 1/4 CORNER COMP GLO SET POST 12" Book A, Pg 12; S. Edson, Book A, Pg 196; Edgar M OCRC WITNESS BOOK! LCRC # 100420, R. Hepw Proration of dist Cen E-W Rd S 1 4" TW Hickory Unrecorded Survey, R. H Fnc to North is 60d Spk SE	78/9, No find find find find find find find find	Oceana County Remonumentation Peer Group Reviewed & Approved Date: 10-13-98 J. Randolph Hepworth Oceana County Surveyor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

The Iron set by me and recorded at LCRC100420 was pulled and discarded by me in April 11, 1994 when I determined that position was not the best location for the corner. In April, 1994, I determined that the best evidence for the position of the corner was the local collateral evidence of the physical center of the east-west road and the old fence to the south. A fence to the north exists, but it is 22' east. Measurements to the 1/16 line occupation lines verify that this is indeed a better location. I no longer support the corner as recorded at LCRC 100420.

I found the JRH 1/2" (24" Iron in the centerline of the east-west ROAD and on the old fence to the south as described in the unrecorded survey. All witnesses are standing and measure good.

I accept the 1/2"x24" Iron as a careful and faithful re-establishment of the position of the original corner.

accept the 1/2"x24" Iron as a careful a	nd faithful re-establishment of	and position to the second	ota locating the positio	n of the corner.
C. Description of monument for Set 4"x20" Harrison Cast Iron Monume Fence to North is 22' East 60d Spk SE Face 60d Spk W Face 20d Spk E Face 60d Spk SW Face	corner and accessories ent, stamped "County Surveyor Oid fence to South & C/L E 4" Tw Ash 209°AZ 4" Clp Ash 157°AZ P Pole 22°AZ 4" Spruce 318°AZ	" and "26457" -W godo 47.58' EE 38.82' EE 61.41' E	OM OM OM OM	Of MICH G I. RANDOLPH HEPWORTH LAND SURVEYOR NO.
Signed bySurveyor's Michigan License No	Havolt 26457	Dat	November 10	1998 26457 LAND