## SURVEY & / REMONUMENTATION

OCT 27 1993

## COMMISSION

OCEANA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR THE CORD

100506

'93 OCT -7 P2:45

For corners in	i initial troduction							
OCEANA (County)	Located in:	Corner Code ##		J.	REGIS	۔ TER OF	Deper DEEDS	Ziv.
1. Public Land Survey	T <u>15NR</u> <u>17W</u> T R	<u>H-7</u>		. •	REGIO	TEN OI		
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous</li> </ol>	T R S T R S T R		Register	of Deed	ls Stam	p & File	e Numbe	er
•	S T R		2	B C	D E F	G H	J K	<u>L</u> !
do hereby certify that under red in lines 1 and 2 above were in current manual of survey instr	pworth f, in a field survey on quirements of P.A. 74, Michigan P.A. on conformance with regulations and uctions of the United States Department.	of 1970, the corner points mention of rules therefore as required in t ment of the Interior, Bureau of La	the 7	-181	89  16	10-10-	14-	-12-
above were in conformance wi Court of Law; established, expressed below:	a Court of Law and/or that the corner ith the rules of the Michigan Board of re-established, monumented, re-m	Land Surveyors or by a Decree of conumented, recovered, found	ofa a	-192	29-28	22-	23	-24-
on this certificate.			12	-31	32 33	-34	35	<del>36-</del>
A Description of original	manument and accessories and	Arr embeddigent restorations						

A. Description of original monument and accessories and/or subsequent restoration:

A. H-7 1/4 CORNER COMMON TO SEC. 15 & 22 HART TWP TISM, R17W GLO SET POST 10° LYNN N070W 33.71 \$520W 26.41 16" BEECH BOOK A - 3 S. EDSON, MAY 1879 20" STONE & CROCKERY PLACED AT GLO CORNER FOUND, NO WITNESS BOOK A-130 S. BDSON 1882 CORNER NOT DESCRIBED OR WITHESSED OCRC WITNESS BOOK: 4-10-51 WELL POINT 10\* ELM NO5ºE 18.3' 8" BLM N450W 42.01 36.01 NAIL TOP OF S PENCE POST NAIL TOP OF FENCE POST 29.801 LCRC # 100162 D. SOUTH, LS 20623 12-17-73 FOUND PK HAIL IN ROAD @ OCRC WITNESS STEEL PIPE PENCE POST S. 33.99' CAP IN TOP OF FENCE POST N 29.80 CAP THUSE SIDE PPOLE SE SWADE 183.70 2 41 UP C C/L END. OF 48P CMP NES 76.60

B.Description of corner evidence found and/or method applied in restoring or reestablishing corner

FOUND 1/2" IRON REPLACEMENT OF D. SOUTH PK HAIL AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

H-7 1/4 CORNER COMMON TO SEC. 15 & 22 HART TWP T15N, R17W

and the second of the second of the second

SET "COUNTY SURVEYOR "HARRISON 4" X20" CAST IRON MONUMENT IN PLACE OF FOUND 1/2" IRON SIACE 4º ELM N72°W 60d SPK 181.41 KDK R/R SPK N FACE POWER POLE S76°W seter 184.51. KDN is time W IACE - POWER POLE 60d SPK --- S540K 99.87 EDK CENTER OF CORNER STEEL PENCE POST S020W 34.00 TAPE SMALL NAIL/CAP LS20623 TOP OLD WOOD POST NO50B 31.19 -POST LEANS 1.61 NORTH W&W 1/2" IRON SOUTH 32.95 TAPE



Signed by Surveyor's Michigan License No. 26457

September 30, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983