SURVEY & REMONUMENTATION /

APR 2 5 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHGAN RECEIVED FIRE DECIMEN

100565

JAN -4 P3:23

For corners in OCEANA		t analad las	Camar Cada add		
	(County)	Located In:	Corner Code ##	Jung & mail	
1.	Public Land Survey	T <u>16N</u> R <u>17W</u> T R T R T R	<u>L-9</u>	REGISTER OF DELOS	
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		egister of Deeds Stamp & File Numbe	
				2 6 5 4 3 -2	
do in cu Ma ab	D. Randolph Hepwor hereby certify that under re- lines 1 and 2 above were in rrent manual of survey instru agement or by a decree of ove were in conformance with ourt of Law; established, pressed below:	4 7 8 9 10 11 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
N	OTE: Not more than 4 con this certificate.	corners, all in the same town a	nd range, may be recorded	11 12 31 32 33 34 35	
A.	A. L-9 1/4 CORNER C	ion of original monument and accessories and/or subsequent restoration: 1/4 CORNER COMMON TO SEC.S 24 & 25 T16N, R17W WEARE TOWNSHIP Date: 1/-18-93			
	OCRC WITNESS, 6-3-52: FENCE POST	: 1" ROUND IRON ON N-S FEN N 34.2' F	J. Rancolph Hepworth Oceana County Surveyor		
	WESTSHORE ENGINEE 8" Fence Post N 31.80		corded survey; Found 1" Iron 1.8' deep, be "W 38.30 6" Fence Post S 32.4	nt raised w/ 1/2" rod 86 6" Fence Post S20°E 34.45	
	B.Description of corne	r evidence found and/or method	l applied in restoring or reestablishin	g corner	
	I found a 1/2" Iron, in the	surface of an east-west paved road	Drainage Ditches and rough Field fences	run North and South from this stake	

Westshore Engineering Co. had discovered a 1" Iron about 1.8' below road surface and had raised with the 1/2" Iron.

GLO calls do not aid in determining this location. No 1/16 line occupation lines exist to aid in the recovery of the corner.

I believe the 1" Iron found by Westshore Eng. to be the same as the 1952 OCRC corner. Road construction during the summer of 1994 destroyed both the 1/2" from and the 1" from. While reestablishing this corner, I discovered at 48" deep from present grade an old Plowshare. The Plowshare fit the witnesses to the 1/2" Iron.


No conflicting evidence or information is available that would lead to another location for the corner. Therefore I accept this found 1/2" Iron being a riser for the plowshare and 1" Iron AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

L-9 1/4 CORNER COMMON TO SEC.S 24 & 25 T16N, R17W WEARE TOWNSHIP

SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT above the plowshare

C/L E-W PAVEMENT	C/L N-S CULVERT	EAST 6		
60d SPK N FACE	POWER POLE/TRANSF	S85°E	594.81	EDM
R/R SPK E FACE	POWER POLE	N70°W	214.63	EDM
60d SPK S FACE	POWER POLE	N80°W	536.11	EDM
chiseled notch top center	er of 30" CMP	164°az	25.95	EDM
chiseled notch top center		06°az	25.03	EDM
16d spk NE Face	4" Fence Post	162°az	34.82	EDM
16d spk W Face	6" Fence Post	177°az	32.74	EDM
16d spk E Face	8" Fence Post	357°az	31.74	EDM
16d spk SW Face	8" Fence Post	323°az	38.44	EDM



26457 Surveyor's Michigan License No.

November 8, 1994

Date