Ogemaw County Remonumentation

FF CONTRACTOR

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FEB & 4 2000

For corners in	Filing	Requirement of Act 74, Mich. P.A	1970 FEB 2 4 2000
Ogemaw (County)	Located in:	Corner Code #	SECTION
1. Public Land Survey	T22N R0 T22N RT TR TR	2E M-10 A-10	
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S TR S TR S TR S TR	Wanda Muzik, Os	Page: 1 of 1 12/27/1999 09:0 Register of Deeds Stamp & File Number
4. Lot No, Recon	ded Plat		
5. Private Claims			
that under requirements of P.A. In lines 1 and 2 above were in contine current manual of survey instructions of Land Management or b mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree recovered, found as expressed below.	/4, Michigan P.A. of 19 formance with regulations of the United State ya decree of a Court of Live were in conformance wo fa Court of Law: establis	and rules therefore as required in es Department of the Interior, aw and/or that the corner points ith the rules of the Michigan Board	3 4 7 8 9 10 11 12 15 16 15 14 13 17 16 17 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19
NOTE: Not more than 2 cor on this certificate	rners, all in the same	e town and range, may be recorded	9
			10 - 30 - 29 - 28 - 27 - 26 - 25 - 31 - 32 - 33 - 34 - 35 - 36 - 36 - 35 - 36 - 36
A. Description of original mo GLO by L. Clason, 1838, P N63W 38 lk 16" Hemlock S31W 48 lk 14" Beech	ost	ies and/or subsequent restoration: Survey by D _. Ledy	13 1986, Found Pk nail
LCRC by T. Lapham, 1985, East 50.62 Centerline Ri West 93.45 Power Pole S50E 74.81 10" Birch	, Found Pk nail W Marker		
LCRC by C. Lindgren, 1989 Set 1/2" rerod w/cap stamp East 50.67 Punch Mark S50E 64.09 24" Maple N80W 93.10 Power Pole	ed MDOT	Consumers Power East 49.35 Power West 93.45 Power	
Survey by N. Caldwell, 1973	3, No material		12-16-94 366
Survey by R. Higgins, 1979	, No material		DATE INITIALS
Survey by R. Higgins, 1979	, Pk nail		
No GLO evidence found. F the same corner used by Co M/A-9 and M/A-11 and was	ound 1/2" MDOT capped onsumers in 1965 even th set approximately 0.9'+- to ons and the method used	ough the witness matches. It appears the existing South of M.O.L. This location is 2.5'+- South of the (fences) is faulty. Therefore the existing found it.	g corner: 5, and 3 - 1989 witnesses. This does not appear to be ng iron was set by single proportionate measure between the Consumers position. No other surveys appear to be ron was accepted as a faithful establishment and the
C. Description of monument Set 5/8"x36" rerod w/ alumin East 50.50 R/W Marker S54E 74.88 10" Paper Bir	num remon cap	cories established to perpetuate locating	he position of the corner:
S30E 127.61 12" Ash West 93.11 Utility Pole East 0.5 Centerline M-			
J. S. OGRETHIE M	 		
Signed by	Sel 1	Erol	17/73/1999
Signed bySurveyor's Michigan License I	No. <u>27595</u>	Date	907711