NOV 01 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Fili	ng Requirement o	f Act 74, Mich. P	P.A. 1970				
For corners in				1				
Osceola	Located In:	Corner Code	#					
(County)	Localed III.	Comer Code	π					
. , , , ,	1	17N 7W	G - 4					
1. Public Land Survey	<u>T</u>							•
•	Ţ <u>F</u>							
	Ţ <u>F</u>	<u> </u>						
0 B	<u> </u>	<u> </u>						
2. Property Controlling	S TR			1				
in Section 3. Miscellaneous	``~` <u>-</u>		····					
Property in Sec.	~		 -					
Property in Sec.	·	<u> </u>			Register o	f Deeds Star	np & File Nu	mber
	,							
4. Lot No, Reco	rded Plat							
5. Private Claims				1	ABCI	EFG	HIJI	C L M
-				2	2 6	<u> </u>	$-\frac{1}{3}$ $-\frac{1}{2}$ $-\frac{1}{2}$	<u> </u>
						ÍÍÍ	ĪĪĪ	
. Robert T Wetherell		A110 7	99					
I, Robert L. Wetherell, in a field survey on Aug. 7, 19 00 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					1 - 7	₿ ─	-10	12-
conformance with regulations and rules therefore as required in the current manual of survey instructions of the					5 		 	
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or					s — 18—— 1	7 16	-1514	13_
that the corner points mentioned								
Board of Land Surveyors or by recovered, found as expressed by		of Law; established, re	e-established, monun	nentea,			_2223	
recovered, round as expressed by	e1044.			Ł	3 -192	1 1		24-
NOTE: Not more than 2 con	ners, all in the same to	wn and range, may be	recorded	g	/	 	+++	
on this certificate.				1	0 30 2	9 28	-2726	25
				1	1			
<u>G-4 - W ¼ Corner</u>	r of Section 10, T17	<u>N, R7W</u>			2 31 3	233	34 35	36
				-				
A. Description of original mo	nument and access	vice and/or eubecaus	ant restoration:	1	.3			
A. Description of original fix	onument and access	nica ana/or subacque	ant restoration.				,	
1848 – O. Lvon #1 – 8" Ironwood S50 #2 – 32" Lynn N81½		Remonumentatio Set 3" Clay Tiles "Stone Marker & #3 – 2" Sugar S2 #4 – 4" Plum N4	Roots O.B.T." 414E 9734 Links		***			
	`	SEE OVER FOR			ŕ			
B. Description of corner evi	idence found and/or r	nethod applied in resi	toring or reestablish	hing corner	•			
I found a ½" rerod in	fence row to East, o	ecupation line to We	st. 1.3' West of C	L of North	and South	Road (M-66)	•	
Condition of the acce	line with							
C. Description of monumen	t for corner and acces	ssories established to	perpetuate locating	g the position	on of the cor	ner:		
I put a Cap (Marker 2 faithful re-establishm	24624) on the $\frac{1}{2}$ " re-	rod and accepted it a f the original corner.	s a substantial ma	rker for the	corner and	is accepted a	a Conful a	nd
	-						100	à.
NW Cor. Cement R/					4	A ROBE	HTL 1	
NE Cor. Cement R/V					7	WETH!	ERELL	E
NE Corner of Cemen		11.40°			4	K LAI SURV		.
20" Apple N62W 12	2.00°					SI SOMY	_ / _	#
					4	24		*
					"	Mark Street		7
	ZUE	Then sel		S	7/-	COL		
Signed by John	~ Wel	nery	Date	e	clo ~	ノノで原教	1000	
Surveyor's Michigan License	No	24024						
, ,	LAND CORNER							
P.A. 3	45 OF 1990		•					
Osce	eola County		FORM APPROVED	BY MICHIGAN	STATE BOARD O	F PROFESSIONAL	. SURVEYORS, J REVISED M	
8.26.	99						REVISE	JAN., 1983
0.01		-					REVISED	OCT., 1995

Liber B page 500

CONTINUATION OF DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUETNT RETORATION.

1957 - State Highway Dept. Corner 1.3' West of C/L.

1998 M. McClung LS 13037
"Set iron 1.3' West of C/L as called for on M.D.O.T. Plans No Accessories given.

99 SEP -3 AMII: 48

SURVEY & REMONUMENTATION

NOV 01 1999

SECTION