FEB 2 5 1950	LAND CORNE	R RECORDATION CERTIFICA	TE
For corners in	্ৰাপ Filing Require	ement of Act 74, Mich. P.A. 19	70
For corners in CONTRACTOR	Located In:	Corner Code -##	ADDDOVED I MAD CODUED
Public Land Survey	T <u>17N</u> R8W T R T R		APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County  Mathewall
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R		Register of Deeds Stamp & File Number
A Lot No. D	annuded Dist		
	ecorded Plat		A B C D E F G H I J K L
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with	uirements of P.A. 74, Michigan P.A. conformance with regulations an octions of the United States Depart Court of Law and/or that the corne the rules of the Michigan Board o	vember '7, , 19 93 of 1970, the corner points mentioned drules therefore as required in the liment of the Interior, Bureau of Land repoints mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	2 6 5 4 3 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 1 1 1 1
expressed below:	restautistied, intofformented, ferti	nonumented, tecovered, todalo as	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.		11 32 33 34 35 36	
A. Description of original monument and accessories and/or subsequent restoration:  The original corner was set by deputy surveyor Orson Lyons on Jan. 6, 1848. Tree for post 40.00 chains from the Southeast Corner of Section 26.  Beech 18" is the corner.  Beech 10" S74W 12 lks.  From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back)			
8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  Found Tile, with 1" pipe inside 8" below road surface. Removed pipe from tile and set at south side of tile. Set Osceola County Monument in center of tile 8" below road surface.			
C. Description of monumer	nt for corner and accessories e	established to perpetuate locating	the position of the corner:
Corner K-10. ( 1" pipe 18" in Telephone Power Pol Power Pol	Osceola County Mon	ument, which is a 3' eet.	of Micano MATTHEW A. McCLUNG LAND SURVEYOR NO. 13037
Signed by Matthe			ovember 6 1993
Surveyor's Michigan License	<b>1/</b> 000	7FORM #	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

17 Marcy Craybed

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

This corner was recorded in the miscellaneous pages of the Evart Twp. Book; as tile and iron, witnesses Apple 16" N31W 50.6 feet and Fence post E. 26 feet, sometime prior to 1939. It is also noted the North 1/2=2633.0'.

I used this corner in 1975, in a survey for Fred Lass, and recorded a PA. 74 certificate.