## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Osceola Located in:	Corner Code #
1. Public Land Survey TR	
2. Property Controlling S 2 T 17N R 9W in Section S 35 T 18N R 9W  3. Miscellaneous S T R  Property in Sec. S T R	2 16 Register of Deeds Stamp & File Num
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
I, <u>Craig W. McVean</u> , in a field survey on <u>Oct. 29</u> , 19 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970 points mentioned in lines 1 and 2 above were in conformance with regu	O. the corner
rules therefore as required in the current manual of survey instructions of States Department of the Interior, Bureau of Land Management or by a Court of Law and /or that the corner points mentioned in lines 3, 4 and in conformance with the rules of the Michigan Board of Land Surveyors Decree of a Court of Law; established, re-established, monumented, rec found as expressed below:	of the United decree of a  5 above were 10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	
A. Description of original monument and accessories and/or subsequent restoration:	
<ul> <li>LCRC L. 2 P. 11 - K. J. Ostling - 1977 - Set 5/8" Bar W/RLS Cap and Cedar Post per Standard Subdivision of Sections. 11" Cherry N15°E 39.1', 20" R. Oak N60°E 70.6', Random due N. 2.6'. E 1/16 on S. Line Sec. 35, T18N, R9W due W. 22.6'</li> <li>- DNR Survey Proj. #75-44 - K J. Ostling - 1977</li> </ul>	16 - LCRC L.2, P. 2 - K. J. Ostling - 1977 Set 5/8" Bar w/RLS Cap and Cedar - post per Standard Subdivision of Sections. 11" Cherry N40°E 49.1', 20" R. Oak N70°E 90.5', E-W Random due N. 2.6', E 1/16 on N. Line Sec. 2, T17N, R9W due E. 22.6' DNR Survey Proj. #75-44 - K. J. Ostling - 1977
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
2 - E 1/16 on N. Line Sec. 2, T17N, R9W - FND. 5/8" Rebar as established by Ostling. This position is not in agreement with Remon. Corners at J1 & K1 T17N, R9W, so I remove Ostling monument and Reset 2" A.C. on 5/8" x 40" Rebar midway between J1 & K1 on on Standard line.	16 - E 1/16 on S. Line Sec. 35, T18N, R9W FND. 5/8" Rebar as established by Ostling. This position is not in agreement with Remon. Corners at J13 & K13, T18N, R9W so I removed Ostling Monument and Set 2" A.C. on 5/8" x 34" rebar midway between J13 & K13.
C. Description of monument for corner and accessories establi	ished to perpetuate locating the position of the corner:
2 - 2" A.C. on 5/8" x 40" Rebar with Ring of Stone SSE 0.65' to Face Reset Cedar Post W 1' to Set Carsonite Post West 29.37' to E 1/16 Sec. 35, T18N, R9W East 22.35' to Spike at KJO position. N57°W 4.07' to N&T in NE Side 6" x 6" Wood Post N60°E 90.87' to Set N&T in SE Side 28" R. Oak (KJO) S77°E 36.52' to Set N&T in S. Side 6" B. Cherry	16 - 2" A.C. on 5/8" x 34" Rebar in Ring of Stone. SE 0.8' to Face Reset Cedar Post SW 1' to Carsonite Post East 29.37' to E 1/16 Sec. 2, T17N, R9W, this being 0.35'S & 0.2 E of Ostling #16 (Removed) N65°E 14.71' to N&T in NW Side 6" x 6" Wood Post N4°E 56.69' to N&T in W Side 7" B. Cherry S50°W 25.00' to N&T in NW Side 8" Poplar
Signed by Crive M. Mu Ven	Date 1/20/1998 0 CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO.
Surveyor's Michigan Úcense No. 39	088 39088 ATTOMATION NO. 100 ATT