DEC 13 2000

LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

	r corners in ceola	, l	ocated in:	Corner Co	de#							
1.	Public Land Survey	,	T 17 N	<u>R9W</u>	L-11					:	_	סכ
			Ţ	R						•) 	<u> </u>
			<u>T</u>	R								
			Т	R					. ^	4.5	7-3:a	
2.	Property Controlling	s	T	R							ë E	35
	in Section	<u>s</u>	T	R		Daniata	. f [.	ِ دلیم	, ,	20 20	골목
3.	Miscellaneous Property in Sec.	<u>s</u>	_ <u>T</u>	R		Registe	eroru	Jeeds	San	праг	-He IVI	umbe
4. 5.	Lot No. Recor	S rded Plat	T	<u>R</u>		, 1	A B	C D !	E F (GH.	IJŀ	(LM
I, Robert L. Wetherell, in a field survey on July 19, 2000, do						2 3	6	5	4	3	2	1
hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner							7	8	9	10	11	12
points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Department of the Interior							18	17	16	15	14	13
States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were							19	20	21	22	23	24
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							30	29	28	27	26	25
						11 12 13	31	32	33	34	35	36
<u>L-1</u> А.	1-4 Corner common to Description of origin	al monum	ent and acco	R9W essories and/or	subsequent restorati	on:						

1838 - J. Hodgson, G.L.O. 1983 - J. Wilcox, LS 14102 1997 - R.L. Wetherell, LS 24624 #1 - 8" Hemlock S32°E 6 Links L.C.R.C. - Liber 02, Pg. 228 L.C.R.C. - Liber 03, Pg. 141. #2 - 16" Hemlock N22°W 14 Links Found 5/8" Rod (1.5' above ground & bent) Survey recorded Liber 621, Pg. 694. #3 - 20" Ash S20°W 29.39" Found clay tile added 1/2" rebar 1891-1904 - Tempell/Trumbull/June #4 - 16" Maple S50°W 25.98" #7 - 10" Maple N30°E 42.52' Remonumented T17N, R9W #5 - Cor. Post N40°W 1.4' #8 - 12" Maple S54°E 82.02' With 3" Clay Tiles. #6 - Fence Post North 11.45' #9 - 12" Maple N52°W 40.46' #3 - 18" Ash S26°W 27.21' 1997 - G. Gray, LS 17741

Survey recorded L. 621, Pg. 622. Same witnesses as Wetherell in 1997.

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found the ½" capped iron (LS 24624) inside a 3" clay tile. The corner is 2 feet South of fence line to the West and in line with fence to the North. I found the 5/8" rod (Wilcox had in 1983) lying on the ground. I do not believe the 5/8" rod was in the tile when Wilcox used it.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in good condition, #4 Found in good condition, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition, #8 Found in good condition, #9 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I replaced the ½" capped iron with a 1" x 18" pipe with Osceola County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

12" Maple N30°E 42.52' (60d spike W. side) #7 12" Tri. Maple S54°E 82.02' (60d spike N.E. side) #8 12" Maple N52°W 40.46' (60d spike N.E. side) #9 18" Ash S26°W 27.21' (60d spike E. side) #3 APPROVED LAND CORNER
P.A. 345 OF 1990
Osceola County

L. J. W.

8-17-2000

Date August 22, 2000

Signed by Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999